

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

Date of writing Report 11 July 1940 When handed in at Local Office 11 July 1940 Port of Cardiff  
No. in Survey held at Cardiff Date, First Survey and Last Survey 10th July 1940  
Reg. Book. 46264 on the Wood, Iron or Steel Screw "Swignon bours." (No. of Visits 2)

TONNAGE:— Built at Hong Kong By whom Hong Kong & Whampoa D. Co. Ltd. YEAR. MONTH. 1919 8  
GROSS 5187 Owners Leam Line Ltd. Owners' Address Ed.  
UNDER DK. 4736 Managers Malden & Phillips, Ltd. (if not already recorded in Appendix to Register Book).  
NET 3722 Port belonging to London

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Roach Destined Voyage  
ellD B or DBa feet; uE&B feet; f feet  
tal capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 24300 Port Cardiff

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined Offered, not

required.

Was a damage report made by anyone else? If so, by whom? Not known.

PAIRS, OR EXAMINATION AS PER RULE, FOR Interim Certificate, requested on account of slight leakage in way of shell frame, port side of No. 4 hold, stated to have developed during heavy weather on the 28th June, 1940, voyage Pipel to Cardiff.

How done:— No. 2 shell frame from after peak bulkhead, port side No. 4 hold examined. Cement box now fitted over two frame spaces immediately below lower deck in way of leakage from shell rivet.

In my opinion the Owners' proposal to defer permanent repairs until a more convenient opportunity, merits favourable consideration, the vessel's efficiency remaining unimpaired. (Copy of Int. Cert. attached.)

PRIMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	E. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

SENT CONDITION OF THE	Bulkheads	Engine Room Skylights.	Copper, or Y.M. (State if on Felt.)
ing of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
ings	Cement or Asphalt	Oil Bunkers	Boats
s & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
ide Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
es	Windless	Hatches	Equipment letter
se Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
itudinals	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
verses	Have Watertight Doors been examined and found efficient?	Treenails	length mean diamr. (on board)
s	Have Ventilators and their Boamings been examined and found efficient?	Breasthooks & Stemson	Rule length size
ons	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
gers	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Bottom Plating		" " at other places	Standing and Running Rigging
the Tanks been examined internally?		Stringers, Clamps & Shelves	Sails
the Tanks been tested?		Salting (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

This vessel, so far as now seen, is eligible in my opinion to remain as classed without fresh record of Survey, subject to permanent repairs being effected to riveting of second shell frame from aft in No. 4 lower hold (p.s.) at Owners' earliest convenience. (Subject also to SR List.)

Fee (per Section 20) £ : : Fees applied for, £ : :  
al Damage or Repair Fee (if any) £ : :  
elling Expenses (if chargeable) £ : :  
d Surveyor's Fee (if any) £ : :  
Received by me, 19

Thank T. Richardson.

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

FRI. 19 JUL 1940

As now Subject



© 2020

Lloyd's Register Foundation

W984-0077