

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

JAN 24 1941

Date of writing Report 19 When handed in at Local Office 21/11/41 Port of NEWCASTLE-ON-TYNE

No. in Reg. Book. Survey held at NORTH SHIELDS Date, First Survey 23rd Dec/40 Last Survey 2nd Jan 1941

75904 on the Machinery of the Wood, Iron or Steel 8th HINDPOOL (No. of Visits 3)

Tonnage Gross 4897 Vessel built at W. HARTLEPOOL By whom W. GRAY & CO. When 1928. 5

Net 3040 Engines made at W. HARTLEPOOL By whom GEN. MAR. ENG. WORKS When 1928.

Nominal Horse Power 505 Boilers, when made (Main) 1928 (Donkey)

No. of Main Boilers 3.88 Owners POOL SHIPPS & CO. Owners' Address (if not already recorded in Appendix to Register Book.)

No. of Donkey Boilers Managers SIR R. ROSE & CO. Port W. HARTLEPOOL Voyage

Steam Pressure in Main Boilers 180 lbs. Surveyed Afloat or in Dry Dock SMITHS PONTOON.

in Donkey Boilers

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. Port

Particulars of Examination and Repairs (if any) Locking Damage TS.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? NO

" " Donkey " " " "

If this was not done, state for what reasons? GS NOT DUE

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Present condition of funnel(s) GOOD

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers?

Has screw shaft now been drawn and examined? YES Is it fitted with continuous liner? YES Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? NO

Has shaft now been changed? NO If so, state reasons

Has the shaft now fitted been previously used? YES Has it a continuous liner? YES Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft 26.12.40 State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 3/16"

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done COMPLETE.

On account of damage stated to have been caused through enemy action (mine explosion) off River Tyne December 1940.

Propeller, outer end of stem bush and outside fastenings of sea connections examined and found in good condition.

Screw shaft (cc) drawn in examined, and found in good condition.

Crank, thrust and intermediate shafts examined and found in good condition.

DAMAGE REPAIRS: 5 intermediate shaft bearing keeps and 1 thrust bearing keep (cast iron) renewed.

All holding down bolts tested and hardened up as found necessary.

Thrust uress gland rescaured.

General Observations, Opinion, and Recommendation: The machinery of this vessel so far as (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.11, B.&H.S. 9.11, L.M.C. 9.11, or L.M.C. 140 lb., F.D., &c.)

seen is digible in my opinion to remain as classed in the Register Book, with fresh record of suwng screw shaft (cc) seen 12.40.

Survey Fee (per Section 29) £ : / : Fees applied for 21 JAN 1941

Special Damage or Repair Fee (if any) £ 55 : 0 Received by me, 19

Travelling expenses (if chargeable) £ : / :

Committee's Minute

Assigned

JUE 11 FEB 1941

As now

Engine Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

1984-0193

All shafting examined after damage sustained from mine explosion.

Intermediate shaft-bearing keels & one thrust-bearing keel renewed.

It is submitted that this vessel is eligible to remain as **CLASSED**. S. 1. 1. 40.

L.F.
7/2/41.



© 2020

Lloyd's Register
Foundation