

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report 24th Nov. 1939 When handed in at Local Office 24 NOV 1939 Port of NEWPORT, MON.

No. in Reg. Book. 09932 Survey held at NEWPORT, MON. Date, First Survey 21st Nov. 1939 Last Survey 21st Nov. 1939 (No. of Visits 1)

on the Machinery of the Wood, Iron or Steel "KINGSTON SAPPHIRE (STEAM TRAWLER)"

Tonnage { Gross 356 Vessel built at Beverley By whom Robt. Wootton & Co. Ltd When 1929-2
 Net 134 Engines made at Hull By whom B. & S. Holmes & Co. Ltd When "

Nominal Horse Power { 96 Boilers, when made (Main) 1929 (Donkey) ✓

No. of Main Boilers 1 Owners Kingston Steam Trawling Co. Ltd Owners' Address "

No. of Donkey Boilers ✓ Managers ✓ Port Hull Voyage ✓

Steam Pressure—200 If Surveyed Afloat or in Dry Dock Commenced 3.0^{pm} Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

in Main Boilers ✓ (State name of Dock.)

in Donkey Boilers ✓

Last Report No. _____ Port _____

Particulars of Examination and Repairs (if any) Prop. & Sigs

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? NO

" " Donkey " " " "

If this was not done, state for what reasons? Boiler not opened out for examination.

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler ✓

Present condition of funnel(s) efficient.

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓

To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓

To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓

, and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓

, and of the Donkey Boiler? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓

, and of the Donkey Boiler? ✓

Has screw shaft now been drawn and examined? NO

Is it fitted with continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? ✓ If so, state reasons ✓

Has the shaft now fitted been previously used? ✓

Has it a continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

State date of examination of Screw Shaft ✓

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 1/16

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Vessel in dry dock. Propeller and all outside fastenings examined & found in order.

Vessel now under Admiralty Control, no information could be obtained regarding the Boilers Survey.

General Observations, Opinion, and Recommendation:— The Machinery of this Vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, E.S. 9,11, E.&M.S. 9,11, L.M.C. 9,11, or L.M.C. 140 lb., F.D., &c.)

so far as now seen is eligible to remain as classified with out fresh Record of Survey.

Survey Fee (per Section 29) £ : : Fees applied for _____
 Special Damage or Repair Fee (if any) (per Section 29.) £ : : _____
 Travelling expenses (if chargeable) £ : : _____

Fees applied for

19

Received by me,

19

Committee's Minute

THE 5 DEC 1939

Assigned

W. J. A. A. A.

© 2019

Engineer-Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

W987-0083