

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 98442

APR 23 1940

(Received at London Office)

Date of writing Report 19 When handed in at Local Office 22/4/1940 Port of NEWCASTLE-ON-TYNE

No. in Reg. Book. 16767 Survey held at South Shields Date, First Survey and Last Survey 8 April 1940
(No. of Visits 1)

on the Machinery of the Wood, Iron or Steel S.S. WYCHWOOD

Tonnage { Gross 2794
Net 1558 Vessel built at Sunderland By whom S.P. Quater & Son, Ltd. When 1934 Month 9

Nominal Horse Power 338 Engines made at Sunderland By whom N.E. Manning & Co. Ltd. When 1934

No. of Main Boilers 2 Spt. Boilers, when made (Main) 1934 (Donkey) ✓

No. of Donkey Boilers ✓ Owners W. France & Son, Ltd. Owners' Address (if not already recorded in Appendix to Register Book.)

Steam Pressure in Main Boilers 200 lb. Managers ✓ Port London Voyage ✓

in Donkey Boilers ✓ If Surveyed Afloat or in Dry Dock Drydock
(State name of Dock.) Middle Dock & Eng. Co. Ltd.

Last Report No. Port

Particulars of Examination and Repairs (if any) Docking.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

" " Donkey " " " ✓

If this was not done, state for what reasons? B.S. not due

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler ✓ Present condition of funnel Efficient.

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓ , and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ , and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓ , and of the Donkey Boilers? ✓

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? ✓ If so, state reasons ✓

Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

State date of examination of Screw Shaft ✓ State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 3/32nds.

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted Light.

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? No.

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? No.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

Now done:- Vessel placed in drydock, propellers and underwater fastenings examined and found efficient.

General Observations, Opinion, and Recommendation: The Machinery of this vessel, as far as now seen, is in efficient condition and eligible, in my opinion, to remain as classed without fresh record of survey.

Survey Fee (per Section 29) £ ✓ Fees applied for 19

Special Damage or Repair Fee (if any) (per Section 29.) £ ✓ Received by me, 19

Travelling expenses (if chargeable) £ ✓

Committee's Minute FRI. 8 MAY 1940

Assigned As now

It is submitted that
this vessel is eligible to
remain as OLAS-ED.

RP
30/4/40



© 2019
Lloyd's Register
Foundation