

Inq. 1.

ISSUED BY THE  
MINISTER OF WAR  
TRANSPORT

## EXAMINATION ON OATH.

IN PURSUANCE OF THE 465TH SECTION OF THE MERCHANT SHIPPING ACT, 1894, 57  
AND 58 VICTORIÆ, CAP. 60.*Frank Douglas Gardiner of 55, Southtown Road.**Great Yarmouth.*

being duly sworn,

deposes as follows; namely,

1. That he, being the holder of a certificate of competence, numbered 009648  
*Master, Foreign Trade*  
 was Master of the Motor ship *Tamagusta*,  
 of the port of London of the gross tonnage of 454.20 tons, her  
 official number being 181,521 ; that the ship was built of Steel  
 at *Savick, Glasgow* in the year 1943, that she was classed by *Lloyd's*.  
 as 100 A1, that her engines were of 385 Brake horse-power,  
*and that she was rigged as*

2. That the ship *is* owned by *William Bartram Cecil-Lowe*  
 of *The Vicarage, Higham*, in the County of Kent.  
 and *was under charter to*

3. That the ship carried a crew of 12 hands including deponent, and four  
*superannuates*. The name of the pilot was

4. That the ship had on board a cargo of eight lorries and two containers  
*containing owners personal effects* of the weight of 29 $\frac{1}{4}$  tons shipped by *Essex Commercial Enterprises*  
 of *Dagenham* and consigned to *S. S. C. de Chauffures Dala, Larne*.  
 of *Tamagusta*, by *lorry* and that 1 lorry of 3 $\frac{1}{4}$  tons of *was* were carried on deck.

5. That the ship sailed from *Dagenham* on her intended voyage to  
*Tamagusta*, by *lorry* on the 13<sup>th</sup> day of *March*  
 1947, at 2 p.m.; that the draught of water of the said ship at the time of sailing was  
 3 feet 6 inches forward and 6 feet — inches aft. *from her* *fully ballasted for the voyage*.

6. That at the time of sailing as above the said ship was well found in every respect.  
 On 13 March 1947, the vessel was fully ballasted for the voyage. A total of 52 tons  
 (less oil, 12 tons) of fresh water and about 10 tons of stores. The water tank was carried  
 on the starboard side forward in foremost wing tank. The life saving appliances consisted  
 on port side aft, in davits, a boat marked for 14 persons, and a boat on the starboard  
 side for 16 persons or of 16 feet, deponent not being certain of the particulars of the starboard  
 boat. A boat unmarked, but about 14 feet was carried in davits on the deck just  
 forward of the fore hatch and not carried in davits. The port and starboard

7. That the said ship was proceeding on the intended voyage as above stated  
 calling at *Southend* for compass adjusting, leaving that place on  
 14 March 1947 at 11.50 a.m. The weather at the time of leaving *Southend*  
 was fresh north easterly wind and a fresh sea. The voyage north  
 the Channel was without incident and *Mahant* was sighted

 RECEIVED  
 5 APRIL 1947  
 MINISTRY OF WAR TRANSPORT

 Lloyds Register  
 Foundation

at noon on 16<sup>th</sup> March 1947, bearing S.6 magnetic about 8 miles. The weather on sighting "Mohant" was strong south westerly wind with rough sea and freshened throughout the day. The vessel was behaving very well and appeared so far as is known was making no water. This was a certain amount of spray and water coming on the weather decks and it was not possible to take soundings. The vessel remained upright.

At daybreak on 17<sup>th</sup> March 1947, the weather was extremely heavy, the wind being about force 7 from the N.W. with heavy seas. It was then observed that the vessel had developed a slight list to port and at the time was pounding heavily but was answering the helm well. The chief engineer was at once instructed to start the forward

[Continued on page 4 if necessary].

8. That on Wednesday the 19<sup>th</sup> day of March 1947, at noon, the weather being squally the wind blowing at force 7/8 from the S.W. the tide being

with a heavy sea from the

the said ship pounding heavy, the port engine gave out, thought to have been caused through lack of lubrication due to the heat. "Empire Slove" had by this time drawn ahead about one mile and contact was found difficult. Contact was eventually made by International Code flag signals about 1.30pm and "Empire Slove" was requested to take "Famagusta" in tow, and as soon as a safety line was got on board "Famagusta". This line was bent on to a thicker one but this was lost due to a sudden strain being put on it. Supposing the idea of getting a line aboard was abandoned and it was decided to get the four supernumeraries and surplus personnel away in a boat to "Empire Slove". When contact had now failed due to the failure of the batteries caused by shorting. The batteries were carried in the engine room and there was some flooding there. A signal was sent by semaphore to "Empire Slove" that the boat was being sent away to her. This message was not acknowledged. The port boat was got ready. It was intended to send away the four supernumeraries, D. I. operator, steward, 2 AB's and the 2<sup>nd</sup> mate. The 2 AB's and 2<sup>nd</sup> mate to return with the boat. The boat was successfully swung out and lowered and was lying alongside and personnel were embarking in it when the wife of the owner refused to embark without her pet dog and insisted upon taking it. In the resultant confusion the 2<sup>nd</sup> Eng and a greaser (Jones) had boarded the boat and the 2<sup>nd</sup> Mate was not there to take charge and someone had cast off the painter before he could get in. The boat got away under oars successfully and made her way toward "Empire Slove" about

200 yards away to leeward. The boat had slipped some water whilst lying alongside, and deponent notices that the occupants were using the hand pump which was working properly and the boat seemed under control. Deponent went forward to get the barley float ready for launching when he heard a shout and on looking round saw that the life-boat had overturned at a distance which was judged to be about 80 yards to leeward of "Empire Slove". Some members of the boat seemed to be swimming towards the other ship and others hanging on to the upturned boat. They were all wearing their life jackets and deponent had no fear for their safety. The remainder of the crew were ordered to get away by barley float. It was then seen that the "Empire Slove" was bearing down toward "Famagusta" and that people were climbing up her side by means of ropes etc. the upturned lifeboat was swept toward "Famagusta" and almost caught between the two vessels but fled clear and some of the people still in the water were probably crushed between the

[Continued on page 4 if necessary].

9. That services to the said ship were rendered as follows:

Attempt to tow and successful rescue work by "Empire Slove"

[Continued on page 4 if necessary].

10. That in consequence of the aforementioned casualty - 6 - lives were lost; that the lives of the master & crew and passengers (in all) were saved by , the survivors subsisting on board that vessel from to when they were landed at

11. That the loss on the said ship is estimated by deponent at unknown pounds sterling, and on the said cargo at unknown pounds sterling and that the ship was insured in the sum of unknown pounds sterling, the cargo in unknown pounds sterling, and the freight in unknown pounds sterling.

12. That in deponent's opinion the cause of the casualty was the water entering the forward store room through the deck causing the initial list which was aggravated by the severe weather.

and that it could not be avoided

13. That the above statements are correct and true to the best of deponent's knowledge and belief and they have been read over to the deponent before he signed.

*R. Lardner*  
Deponent.

Sworn at London  
26<sup>th</sup> day of March 1947.

*M. Longman*

before me  
Officer of Customs and Excise  
Officer of the Coastguard  
Person appointed for the purpose  
under S. 465 of the M.S.A. 1894.



© 2020 Lloyd's Register Foundation  
Lloyd's Register

[Continued from paragraph 6 page 1.] The forward boat was a tanked boat but not equipped. There were 16 standard Kapok type life jackets distributed. All other life saving appliances were in complete order. The pumping arrangements <sup>for the forward part of the vessel</sup> were forward and were electrically controlled and were largely inaccessible in bad weather. An objection to this was made by deponent and his objection was partly met by arrangement being fitted whereby it could be controlled from aft. About the middle of January, the deponent was informed that there would be four people travelling in the vessel in addition to the twelve members of the crew. The four additional people were squeezed into the existing accommodation while ~~the~~<sup>the</sup> two members of the party were accommodated in the steering flat. There was a Carley float on the fore hatch and a small buoyant apparatus on the bridge deck aft.

(Continues from Paragraph 7 page 2).

Double Bottom suction pump. A small quantity of water was pumped out, but this did not counteract the small list the vessel had. The deponent assumed then that the list was caused by the weather being on the starboard side. The list did not develop during the day although the weather was getting worse, but the vessel was pounding heavily and rolling about and shipping water. During the night of 17<sup>th</sup> March 1947 the weather increased and the list to port increased and by about 6 am 18<sup>th</sup> March, the list had increased to about 9 degrees. During the night of 17<sup>th</sup> March, the deponent instructed the Chief Engineers to go forward and start the forward pump. He returned and reported that there was water in the fo'c'sle room and over the forward hatch and that the forward pump was out of action, owing to the water. The after pump was then connected to the double bottom. A good suction was obtained. The chief engineer also reported that water was coming through the weather deck <sup>around</sup> the companion way, Hatch way and after bulk head. Throughout the night the weather remained from ahead to about 2 points on the starboard bow.

On the morning of the 18<sup>th</sup> March, when the list of about 9 degrees to port was <sup>noted</sup> increased, the deponent instructed the Chief Officer to go forward and examine the fo'c'sle room and report, but when he reached the companion way he was in such danger of his life that deponent recalled him. The chief officer stated he could hear a considerable amount of water sloshing about. Throughout the 18<sup>th</sup> March, all possible pumping power was kept going and the vessel's engine speed maintained. In the afternoon of the 18<sup>th</sup> March, the deponent discussed with the chief engineer the possibility of fitting the starboard after double bottom, <sup>completing</sup> <sup>but</sup> as this would entail the stopping of the pumping, deponent decided that pumping was more important.

FILE NO. 19

5

(Continues from paragraph 7 page 4.)

*D.W.*  
The owner, who was aboard, was a qualified engineer, and ~~and~~ discussions with the Chief Engineer, was carried out through him.

As an alternative to filling the after double bottom the possibility of filling the starboard wing tanks was discussed but this idea was abandoned as not be practical.

It was impossible to sound the tanks owing to the heavy seas coming aboard.

*O. D.*  
About noon of the 18<sup>th</sup> March, it was reported to deponent that water was coming aft through the rudder port glands. Deponent's examination disclosed that the glands were loose, and these were tightened down by the ship's engineers, and although this did not entirely stop the leaks, the amount of water which still entered was slight, and could well have been kept down by ~~an~~ <sup>additional</sup> pump if available. The list by this time had increased to about 15 degrees.

By about 6 pm, 18<sup>th</sup> March, the list was about 20 degrees, and a wireless urgency message was sent out requesting any ship in the vicinity to stand by. The message was acknowledged by the "Empire Plover," who reported she would make for "Famagusta" position. The deponent feels certain that the cargo had not shifted. The boxy carried on deck was still in her original position.

The course and engine speed was maintained during the night of 18<sup>th</sup> March. The hatch covers and ventilator covers were still intact and secure.

At 3.30 am 19<sup>th</sup> March, the "Empire Plover" came up to "Famagusta" and stood by. Deponent promised to report the position at daybreak. About 6 am 19<sup>th</sup> March the list was about 23 degrees. The weather was very bad, wind S.W. about force 8, with very heavy seas and squally. Deponent altered course at 6 am to make for Corunna, course made was SxW magnetic, bringing the weather a little more on the starboard bow.

During the forenoon of the 19<sup>th</sup> March, the list gradually increased. The pumps were kept working all the time. The vessel was making 2/3 knots and deponent had hopes of making Corunna under his own power.

6  
(continued from paragraph 8, page 3.)

two vessels. The "Empire Slover" struck the "Famagusta" with at her port bow on "Famagusta's" starboard beam. The 2<sup>nd</sup> mate having boarded "Empire Slover" the two vessels drifted apart. The barley float was launched and Chief Engineer, Mate and one A.B. boarded it. The deponent with the remaining crewmen launched the buoyant apparatus. Both the barley float and buoyant apparatus were picked up by a boat launched from "Empire Slover" and, <sup>occupants</sup> successfully transferred to that ship.

When deponent got on board "Empire Slover" he discovered that one of the supernumeraries had been saved (Mr. Robinson), Greaser Jones, 2<sup>nd</sup> Engineer Pepper <sup>and wireless operator</sup> had been saved from the original boat party. The 2<sup>nd</sup> Engineer was suffering from a ~~broken~~ crushed leg and other injuries from which he has since died.

The persons lost are Mr. & Mrs. Lowe (owner and his wife) who were last seen clinging to the upturned lifeboat, one at either end with the dog on the upturned boat. Mr. Lowe was apparently making efforts to get to the assistance of his wife. Also lost was Mr. Hunter, (a supernumerary) believed crushed, A.B. Abbott (believed crushed). Cook-Steward Brineat (drowned). Five all told, in addition the 2<sup>nd</sup> Engineer later in hospital at Fiume.

"Empire Slover" made search for the missing people without success.

Deponent would like to place on record the bravery of able-seaman Kelly of "Empire Slover" who lost his life in repeated gallant attempts to save the lives of personnel of the upturned boat and generally the whole ships company of "Empire Slover" for the excellent work done in rescue work.

The abandonment was carried out at 3 pm 19<sup>th</sup> March, and prior to this the starboard engine had been stopped and the heat was increasing rapidly. It was reported to deponent that water was entering in the engine room rapidly. The engine room was flooded out.

The approximate position of abandonment was. 44° 22' N. 8° 20' W.

The survivors were landed at Falmouth on Friday 21<sup>st</sup> March.

During the afternoon of 18<sup>th</sup> March it was reported to deponent that water was getting in to the crew quarters on the Port side. He investigated and found that the water was making its way in between the angle bar and the deck bottom of the deck house side and the deck. This was baled but the quantity of water could not be kept down. The deck edge was at that time awash.

Prior to the commencement of the voyage it was desired to inspect the rudders and propellers, because of the vessel having been in the ice at Boston, Maine. The forward tanks were flooded to tip the vessel but as she could not be tipped enough the tanks were pumped out and it was decided to put her on the

C. &amp; E. No. 584.

Enclosure No.

FILE No. —<sup>19</sup>7-  
[7]

(continued from para 8, page 6).

hard for inspection. The morning following the tipping the deponent discovered that the vessel had trimmed a little by the head. Deponent ordered the Chief Engineer to pump out the double bottom port and starboard under the stoke-room and a small amount of water was pumped out. The vessel was put on the hard and the propellers changed and rudder lengthened. At low water it ~~was~~ appeared that a trickle of water was coming from the vessel in the vicinity of the sea suction. On examination of the tank inside the sea suction flange was found to be loose and this was made good by the engineer.

Deponent understands that the owners had made arrangements with Lloyds Surveyors to examine the ship while she was on the hard, but so far as deponent is aware no examination was made when the vessel was high and dry.

D. L. Anderson.

B. Longman



© 2020

Lloyd's Register  
Foundation

W692 - 0129 S/S