

REC'D NEW YORK JUN 28 1948

No. 972

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office

116 JUL 1948)

Date of writing Report 25th May 1948 When handed in at Local Office 19 Port of Aruba, N.W.I.
 No. in Survey held at Aruba, N.W.I. Date. First Survey 20th May Last Survey 21th May 1948
 Reg. Book. 22399 on the Machinery of the Wood, LXXX Steel SS "DEAN EMERY" (No. of Visits 2)

Gross 666h Vessel built at Chester, Pa. By whom Sun S.B. Co. Year. Month. 1919 11
 Net 111.8 Engines made at Chester, Pa. By whom Sun S.B. Co. When 1919 11
 Nominal 612MN Boilers, when made (Main) 1919 (Donkey)
 of Main Boilers 3 Owners Panama Transport Co. Owners' Address
 of Donkey Boilers ✓ Managers (if not already recorded in Appendix to Register Book.)
 Steam Pressure 190lbs If Surveyed Afloat or in Dry Dock Afloat Port Panama Voyage
 in Main Boilers 190lbs (State name of Dock.) San Nicolaas Harbour
 in Donkey Boilers

st Report No. Port Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Particulars of Examination and Repairs (if any) Boiler repair
 Medical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Is a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

Do not state for what reasons

At special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

What parts of the Boilers could not be thus thoroughly examined?

Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?

Has the screw shaft now been drawn and examined? Has it a continuous liner? Is an approved oil retaining appliance fitted at the after end?

Has the shaft now been changed? If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft State the wear down in the

Is electric light and/or power fitted? If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Vessel afloat in San Nicolaas Harbour, Aruba, N.W.I.

At request of the Owners' Representatives, attend on board to examine the starboard boiler in way

port combustion chamber.

Several lap fractures in flanging of tube plate to wrapper plate.

acks veed out examined and welded.


Examined on completion and found satisfactory.

General Observations, Opinion, and Recommendation:—
 (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11 *LMC 9,11 or *LMC 140 lb., FD, &c.)
machinery of this vessel, so far as now seen, is in safe order and condition, eligible in my
opinion to be continued as classed without fresh record of survey,

Fee (per Section 29) £ : : Fees applied for 26.5.1948
 Damage or Repair Fee (if any) Rep. Fls. 100.00
 (per Section 29.) Late fee 25.00
 Ling expenses (if chargeable) £ : 3.00
 Received by me, 19

Committee's Minute As now
 med

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation

Insert Character of Ship and Machinery precisely as in the Register Book. If so, to be sent to