

Report of Survey for Repairs, &c., of Engines & Boilers.

No. 8283

Date of Writing Report 18 January 1891 Port of West Hartlepool

Received at London Office WED 21 JAN 11

No. in Reg. Book. Survey held at West Hartlepool Date, first Survey 15th January Last Survey 15th January 1891
 22 on the Machinery of the Scow Steamer "Bakun" Master Beyer No. of Visits 3
 Gross 1669 Tonnage 1093 Vessel built at West Hartlepool By whom W Gray & Co When 1886-6
 Registered Horse Power 200 Engines made at West Hartlepool When 1886 Boilers, when made (Main) 1886 (Donkey) 1886
 No. of Main Boilers Two Owners J Stuart Port London Voyage Batoum
 Steam Pressure in Main Boilers 150 lbs If Surveyed Afloat or in Dry Dock With Eastern Graving Dock Class of Vessel & Machinery +100A1. 11.90
 in Donkey Boiler 90 lbs (State name of Dock) and Victoria dock As in Register Book, including dates of Special Surveys of Ship and carrying bulk
 5.5 H.P. 11.90 Petroleum in bulk

Last Survey No. Port

Particulars of Examination and Repairs (if any) Excluded after Collision & Grounding + L.M.C. 11.90

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time? No

If this was not done, state for what reasons? Not open for survey & recently surveyed

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler?

Vehicle placed in Graving dock. Examined Propeller, Propeller shaft, stern bush and sea connection fastenings and found all satisfactory.

The backs of Combustion Chambers were slightly bulged in places and stays to same had been leaking around riveted heads, in my opinion caused through dirt; 40 screwed stays (18 in Port and 22 in Starb^t) have been taken out, and replaced with stays, fitted with Nuts.

State if a Report is also now sent on the N.S. or if not when, and where, can it be seen.

Insert Character of Ship and Machinery presented on in the Register Book.

General Observations, Opinion, and Recommendation:—The Engines and
 (State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey:
 —thus, for example, D.S. 1/89, B. & M.S. 1/89, or L.M.C. 1/89, as the case may be)

Boilers of this vessel, so far as seen, are now in a safe working condition, and eligible, in my opinion, to remain as classed.

Office or Registration Fee (per Sec. 27)
 Survey Fee (per Section 28)
 Special Damage Fee (per Section 28)
 *Certificate (if required) as per margin
 Travelling Expenses (if chargeable)

: : :
 : : :
 : : :
 : : :
 : : :

Fees applied for
 18
 Received by me,
 18

Thomas R. Blackie
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute 53 JAN 01

Assigned Remain as classed

The Surveyor is required not to write on or below the space for his Name & Signature.

Offices 1890, 1912, 1913

© 2018



Lloyd's Register
Foundation

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

This document has been
is legible to remain
as desired

M.A.
22-1-91

LR-FAF-SA16-53

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2018

Lloyd's Register
Foundation