

Nov. 33005

Newcastle

—st March 1896.

J. Hilton & J. A. Hale

The Committee represented us on the
W.H. Williams and subsequently, on some
of the several steamship companies of
London, as the best agent in the United
Kingdom about which to send you and
report upon the damage which it have
been suffered by the loss of timber, etc.
on the voyage from America, this cargo
in ballast and back to Liverpool having
fully loaded, between the 2^d Feb^d "95
1895 and 25 Jan^r 1896.

Sympodus monticola leg. Rom
and protat.

On examination found big Ventilator
gone, took havers and grubbing about
Hunting gear found and a partly gone
wheel chain broken, wooden stem
whale pipe carried away, funnel guy
rope gone out, cutting the double
bottom at 100' and found twelve
holes

A small metal fastener or screw, possibly made of brass or steel, with a decorative head and a threaded shank.

(2)

welds to bracket plates, started and
leaky as follows - Viz.

In No 2 oil tank one rivet broken and
leaky.

- No 2 oil tank - two rivets started leaky,
- No 3 oil tank - one rivet started & range
in two bracket's leaky.
- No 4 oil tank four rivets started.
- No 5 oil tank two rivets started & range
in bracket leaky.

Rivets in foot of stemelson in summer oil
tank started, electric cable twisted in
place and stands in man hole door of
No 4 oil tank stripped.

Recommended the oil tank cover
hull to be scraped out, cleaned and dry
of gas, the double bottom then to be tested
and repairs to be done to vessel as follows.

Viz - six lost ventilators to be renewed,
damaged tank casings and gratings
around steering gear to be made good,
wheel chains to be overhauled, windlass
steam exhaust pipe and forward gear eye
bolt to be renewed, the bolted and broken
rivets in double bottom tank, ten in number,
to be taken out and seven top bolts fitted
in their place and caulking in way of same
overhauled, the leaky angles at brackets to
double

(3)

double bottom, three in number to be
carefully overhauled and caulked, fit
of insulation in summer oil tank to be
re-wired, chafed electric cable to be renew
and damaged man hole door to No. 4 oil
tank to efficiently repaired, so as to put
this vessel into as good a condition as
she was originally.

G. M. Hake

6.0
FT 17.0

Double bottom
and insulation
in summer oil tank
to be renewed
and repaired
so as to put
this vessel into
as good a condition
as she was originally.
Man hole door to
be renewed and
caulked, fit
of insulation in
summer oil tank
to be renewed and
repaired, so as to put
this vessel into
as good a condition
as she was originally.



© 2018

Lloyd's Register
Foundation