

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report

No. in Reg. Book

Survey held at North Shields Date, First Survey 3rd Sept. Last Survey 14th Sept. 1895
on the Wood Iron or Steel Sc 5" Baku Standard" (No. of Visits)

21. 9. 1895 Port of Newcastle Master

30 TONNAGE: Built at Newcastle By whom Sir W G Armstrong Mitchell & Co When 1893 - 2

GROSS 3708 tons; uE&B tons; f tons; tons; tons.
UNDER D.K. 3385 FPT tons; A.P.T. tons; MT tons; tons.

NET 23785 Owners' Address Anapra Co (Lima) (a Luar M.) Port belonging to London

Surveyed Afloat or in Dry Dock? Afloat Name of Dock River Tyne Destined Voyage

WB=CellDBorDBa

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 1323 Port Nav

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage Repairs. Vessel having collided -

Surveyed by Mr. Menzies on behalf of the Underwriters.

Repairs now done as follows. Viz. vessel lying afloat,

On port bow - Five shell plates taken off, fairing and replaced. five

others fairied in place. ten frames and ten reversed frames

fairied, four beams cut out new knees welded on, four other

beams cut loose & fairied in place. One stringer plate fairied

and doubled, one stringer plate renewed, shift of gunwale

angle renewed, five brackets to frames renewed.

Collision bulkhead fairied and additionally stiffened by 3

horizontal plates $13 \times \frac{1}{2}$, connected to hold stringers by substantial

brackets. All new work coated - fore peak tested with water

and found satisfactory -

| SUMMARY OF DAMAGE REPAIRS:- | Plates. | Frames. | R. Frames. | Floors. | Beams. | Other Items: |
|-----------------------------|---------|---------|------------|---------|--------|----------------------------------|
| Renewed ... | 10 | 10 | 10 | - | 8 | One stringer plate renewed and |
| Fairied or Repaired ... | | | | | | one doubled beam as noted above. |

| PRESENT CONDITION OF THE VESSEL | Number of Frame at the openings | Not seen | Rudder | Worn seen Good | Hatches |
|------------------------------------|---------------------------------|-----------------|--------|----------------|---------|
| Decks | ditto | at other places | - | - | Good |
| Astarways | - | - | - | - | |
| Amidships | - | - | - | - | |
| Pr. Dk. Beams & Fastenings | Where seen | - | - | - | |
| Pr. Dk. Beams & Fastenings | seen | - | - | - | |
| Pr. Dk. Beams & Fastenings | good | - | - | - | |
| Pr. Dk. Beams & Fastenings | Not seen | - | - | - | |
| Windlass & Capstan | - | - | - | - | |
| Pumps | - | - | - | - | |
| Sluice Valves | - | - | - | - | |
| Watertight Doors | - | - | - | - | |
| Dblng. Plates under Sounding Pipes | - | - | - | - | |
| Engine Room Skylights | - | - | - | - | |
| Coal Bunker, Open'gs, Lids, &c. | - | - | - | - | |
| Scuppers | - | - | - | - | |
| Cargo & Main H'tch'ys | - | - | - | - | |
| Hawsers & Warps | - | - | - | - | |
| Standing & Running Rigging | - | - | - | - | |

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9.91," or "to remain as classed and to have record of survey, 9.91, and the notations of 'No. 1-91 and p1ND91, &c.'

This vessel being now in a good and efficient condition, as far as could be seen as she lay afloat, is eligible in my opinion to remain as classed without fresh record of survey.

Fee (if chargeable) per Scale II, Sec. 27 £

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Committee's Minute

Character assigned

Fees applied for,

Received by me,

18

18

18

Surveyor to Lloyd's Register of British & Foreign Shipping.