

10 THUR. SEP 1903

No. 1191

REPORT of SURVEY for REPAIRS, &c.

Date of Writing Report 28.8.1903 When handed in at Local Office 29.8.1903 Port of PHILADELPHIA.

Survey held at PHILADELPHIA

Date, First Survey 29.7.03 Last Survey AUG 20th 1903

the Wood, Iron or Steel S.S. Baku Standard Master H. Lucke

Built at Newcastle By whom Sir W.G. Armstrong Whitworth 1893-2

Owners European Petroleum & Co Ltd Port belonging to London

Owners' Address J. Clark

(if not already recorded in Appendix to Register Book.)

at or in Dry Dock? Yes Name of Dock Gramps 812 Destined Voyage Copenhagen

for DBA feet; uE&B feet; f feet; t tons; FPT tons; APT tons; MT tons

operations in the existing records should be underlined.

has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides cleaned. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, inner bottom plating, especially in the boiler space.

State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER
For Special Survey,
Date of Survey and of
Periodical Surveys.YEAR
Year assigned
to SurveyMachinery and Boiler
Surveys
(including date of N.R., if any).+100 41
spar deck 703

Carry petrol in bulk

SS 112 102.02

Society's Freeboard (if assigned) as
painted on Ship and now verified

Port, No. 15546 Port Due

also whether the Surveyor has made a special damage report he is required to state whether he offered his services for this purpose, and by whom

also whether any damage report was made, and, if so, by whom? by undersigned

EXAMINATION AS PER RULE, FOR Damage by collision with ice

Examination in dry dock, found bottom crushed in on port

from keel up to including F stanche extending from after

of stem to fore side of first cofferdam.

is now done on account of damage.

Le. Plate/Steel stanche no 1 out-faireed, no 2 fairing in place

A no 2 renewed, 10/12/03

B 172 no 3 out-faireed replaced

C 172 no 394

D 172 no 394

P.T.O

IMAGE REPAIRS:-							
	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.
1 Fairing or Repaired	8	23	21	6	1	1	1
2 Fairing or Repaired	8	3	2	1	1	1	1
3 Fairing or Repaired in place	5	10	1	1	1	1	1

SECTION OF THE Vessel		Wood		Copper, or Y.M. of Wood Vessels		Copper, or Y.M. of Wood Vessels	
1. Stringers		Eng. Plates under Sounding Pipes		Copper		Copper	
2. Inner Bottom Plating		Engine Room Skylights		or		or	
3. State if Tanks have been examined inside		Oil Bunkers, Open'gs, Lids, &c.		Wood		Wood	
4. State if Tanks now tested	Yes	Scrapers					
5. Bulkheads		Cargo Hatchways					
6. Ceiling		Matches					
7. Cement or Asphalt (State which.)		Planking of Wood Vessels					
8. Rudder		Caulking ditto					
9. Windlass		Treemalls ditto					
10. Have Pumps now been examined and found efficient?	not ev	Breasthooks & Stays ditto					
11. Have Sluice Valves now been examined and found efficient?	more	Transoms, Pointers, & Catches ditto					
12. Have Watertight Doors now been examined and found efficient?		Timbers of Frame at opening ditto					
		Ditto ditto at other places ditto					
		Stringers, Clamps & Shelves ditto					
		Salting ditto					
		(State if examined.)					

Observations, Opinion as to Class, Recommendation, &c.:—

to clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of 98," or "to remain as classed and to have record of Survey, 1903, and the notations of No. 1-98 and p1ND98, &c."

This vessel is now in good sufficient condition and able in our opinion to remain as classed to have record of Survey 1903 in the Register Book.

Fees applied for, 20.8.1903

Received by me, 20.8.1903

FRI. 11 SEP 1903

TUES. 27 OCT 1903

Deferred until 1st Nov 1903

Lloyd's Register Foundation

Send airmail

Deferred until 1st Nov 1903

Lloyd's Register Foundation

Deferred until 1st Nov 1903

s.s "Baku Standard"

Damage control

Port side. Plates, E stoke no 1-2 & 3 out faired replaced

- . E . no 4 out renewed

- . F . no 1 & 2 faired in place

21 frames reverse frames cut out renewed

6 floors cut out renewed

3 " . . . faired replaced

To - . . . faired in place

One web frame cut out & part renewed

Two beams in fore peak out faired replaced

Fore peak bilge struts cut out renewed

Two plates in collision bulkhead frames cut out & renew

Bilge keelson side keelson in hole cut out and
renewed for 25 ft & 14 ft respectively.

Bilge pipes in way of repairs removed & replaced.

Cement & close ceiling in way of damage renew

Fore peak tested with tank of water.

Repairs due to tear wear. A number of holes made
in starboard side of fore peak, cut out renewed.

A damage report is issued on this case.

Robert Haig

James Cunningham

NOT
char ab
Carrying school in bulk

N.B.-If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side.