

H. 90. 3. dec. 2. 05. - Box held at end of April. (Approved)
New New Sharp filed. in June.

N.B. - If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that
this vessel is eligible to
remain as OLANNAH. Subject to a new
propeller being fitted

H. S. B. ms. S.
17. 3. 06.

LR-FAT-5A-20-7

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

1. 5 6 6 2 = 6 0 1 0 4 = 3

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

SAT. 17 MAR 1906

Date of writing Report 19... When handed in at Local Office 16 MAR 1906 10 Port of Newcastle on Tyne

No. in Reg. Book 36 Survey held at North Shields Date, First Survey Mar 5 Last Survey Mar 7 1906 (No. of Visits 3)

on the Machinery of the Wood, Iron or Steel of Is Baku Standard Master

Tonnage Gross 3708 Net 2375 Vessel built at Newcastle By whom W. G. Armstrong & Co. Ltd When 1893 - 2

Registered Horse Power 298 Engines made at Newcastle By whom W. G. Armstrong & Co. Ltd When 1893

No. of Main Boilers 253 Boilers, when made (Main) 1893 (Donkey) 1893

No. of Donkey Boilers 1 Owners European Petroleum Co. Ltd Port Rusden Voyage

Steam Pressure in Main Boilers 160 lb If Surveyed Afloat or in Dry Dock Smiths no 5554 (State name of Dock.)

in Donkey Boilers 90

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER for Special Survey, Date of last Survey and of Periodical Surveys.	Years Assigned to special survey.	Machinery and Boiler Surveys (including date of N.B., if any).
+100A1		+RMC
Sfordk-9-04		7-02
Carey Petros in bulk		BS-9-04
4 nuc. no 2-02		

Last Survey No. Port Particulars of Examination and Repairs (if any) Tail Shaft

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarized at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Not required also whether any damage report was made, and, if so, by whom? Rumpf of members of

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? no

Do. " Donkey " " " " no

If this was not done, state for what reasons? Not opened out for survey

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓, and of the Donkey Boiler? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓, and of the Donkey Boiler? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓, and of the Donkey Boiler? ✓

Has the screw shaft been drawn and examined at this time? Yes If spare screw shaft fitted, state whether new? Spare shaft (new) fitted

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? about 1/8"

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? It was arranged that the

old spare propeller should be removed & replaced by a new propeller upon the

Vessels return, in 3 or 4 months time, when it is understood that arrangements

have been made for the RMC to be held

Now done Tail shaft drawn examined found evidence that the propeller

had slacked lock on shaft, key way being slack, & also evidence of slight flaw

along the key way at fore end & also in fore end of key way of propeller, cone end of shaft

is also slightly wasted in way of aft end of aft line. The defective shaft has now

been replaced by the spare shaft (Claydon no 8677-B. R.H. 25.1.99. As time would

not permit of a new propeller being made the Superintendent has had the old propeller fitted

and has undertaken to replace it by a new one when the RMC is held,

outside fastenings examined,

Damage stated to have been caused by recent heavy weather.

General Observations, Opinion, and Recommendation:—
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boiler, working pressure, &c.; thus, for example, B.S. 9.99, B.S. 9.00, or L.M.C. 9.00, 140 lb., E.D., &c.)
In my opinion the machinery is now so far as seen in good

condition and eligible to remain as classed with record of new Tail shaft

fitted. 3-06- provided the postponement of the boiler & machinery survey has

met with the Committee's sanction—

	£	s	d	Fees applied for
Office or Registration Fee (per Sec. 27)				19
Survey Fee (per Section 28)				19
Special Damage or Repair Fee (if any) (per Section 28)				
Travelling Expenses (if chargeable)				
				Received by me,
				19

Leonard Challers
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

TUES. 27 MAR 1906

WED. 6 JUN 1906

State if Certificate is required
Committee's Minute
Assigned Deferred

TUES. 20 MAR 1906

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

Character of Ship and Machinery precisely as in the Register Book.

Certificate to be sent to