

At home 6.15 partly cloudy  
Completed 7.30. Off today.

*It is submitted that this*

N.E.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side.

~~the 1st 100 sales have been at 10% off~~

1

22-6-15

LR-FAF-SA20-130

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

SAFETY SURVEY 1916

Date of writing Report	15th June 1915	When handed in at Local Office	JUN 16 1915	to	Port of NEWCASTLE-ON-TYNE.
No. in g. Book.	Survey held at Newcastle-on-Tyne	Date, First Survey	May 31	Last Survey	14th June 1915
64	on the Machinery of the Wood, Iron or Steel S. S. "Baker Standard" Master	(No. of Vessel)			
Gross 3708	Vessel built at Newcastle	By whom	W. J. Armstrong Mitchell & Co. 1893-2	TRIM. MONTH.	
Net 2375	Engines made at	By whom	Walsoken Shipway When 1893		
registered 293	Boilers, when made (Main) 1893	(Donkey) 1907			
use Power 2	Owners (Jacobs & Co. Mys.)	Port Swansea	Voyage Admically charter		
of Main Boilers 2	If Surveyed Afloat or in Dry Dock Mercantile		Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).		
of Donkey Boilers 1			CHARACTER, Date of Special Survey, Date of Land Survey and of Particular Surveys.	Machinery and Boiler Surveys (including date of R.B. if any).	
Steam Pressure— in Main Boilers 160 lb.			+ 100 ft 1 spad m	+ 2966 6, 14	
in Donkey Boilers 100 lb.			7, 13 carrying fuel	95 6, 14	

1st Report No. Port

## Particulars of Examination and Repairs (if any) docking 1 PT BS.

Medical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and repairs being detailed in the body of the report, should be briefly summarised at the end of the report. State also the uses and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Was a damage report made by anyone else? If so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do.

"

Donkey "

"

"

his was not done, state for what reasons?

what parts of the Boilers could not be thus thoroughly examined?

what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

the Surveyor examine the Safety Valves of the Main Boiler?

yes

To what pressure were they afterwards adjusted under steam? 165 lbs

the Surveyor examine the Safety Valves of Donkey Boiler?

yes

To what pressure were they afterwards adjusted under steam? Not adjusted

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

yes

, and of the Donkey Boiler?

yes

the Surveyor examine the drain plugs of the Main Boilers?

yes

, and of the Donkey Boiler?

yes

the Surveyor examine all the mountings of the Main Boilers?

yes

, and of the Donkey Boiler?

yes

screw shaft now been drawn and examined? No Is it fitted with continuous liner? ✓ or two liners? ✓ or is it without liners? ✓

shaft now been changed? ✓ If so, state reasons ✓

shaft now fitted new? ✓ Has it a continuous liner? ✓ or two liners? ✓ or is it without liners? ✓

the distance between lignum vits of stern bush and top of after bearing of screw shaft? 1/8"

Survey is not complete state what arrangements have been made for its completion and what remains to be done? To complete the survey the safety valves of the donkey boiler are to be adjusted at the first opportunity.

The Propeller & fastenings of sea connections examined.

The main & donkey boilers & their mountings examined and the safety valves of main boilers adjusted. A number of small cracks & holes places in main furnaces electrically welded, these furnaces round somewhat distorted but efficient, a few wasted rivet heads at bottom seams of main boilers electrically welded. A few defective tubes in donkey boiler renewed & one screw stay not pointed.

General Observations, Opinion, and Recommendation:— The machinery of this vessel Date clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 11, B.M. 9, 11, or C.L.M. 4, 9, 11 160 lb., N.D., &c.)

far as seen is now in good order & safe working condition & liable in my opinion to remain as classed the rotation of 6.15 being deferred for completion of survey.

Fee (per Section 58)	£2.0.0	Fees applied for	JUN 18 1915
Damage or Repair Fee (if any) (per Section 58)	£ . . .	Received by me,	22/6 1915
ing Expenses (if chargeable)	£ . . .	23/6 1915	

Thomas Leed

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI.JUN.25.1915

FRI.31MAY.1916 TUE.-6MAY.1917

Signed

as per.

FRI.17AUG.1917

FRI.14JUL.1916 FRI.22JUN.1917

FRI.21JUL.1916

FRI.18JAN.1918

FRI.4-AUG.1916

Insert character of ship and machinery previously as in the Register Book.

For a Certificate required if so, to be sent to the Register Office.