

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 24th July 1917 When handed in at Local Office

25 JUL 1917

Port of

NEWCASTLE-ON-TYNE

No. in Reg. Book Survey held at Newcastle
 1905 on the Wood, Iron or Steel Sc. 3 Mat. S. "Stettin". Date, First Survey and Last Survey 24th July 1917
 TONNAGE:- Built at Glasgow By whom Barclay Curle & Co Master J. W. Rose
 GROSS 876 UNDER 557 Owners (J. Currie & Sons) When 1864 YEAR 11
 NET 528 Owners' Address Port belonging to Leith
 (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Afloat Name of Dock River Tyne

WB=Cell DB or Dba feet; uEgB feet; f total capacity tons. FPT tons; APT tons; MT feet feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 79106 Port

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? *Intern certificate* Was a damage report made by anyone else? If so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE FOR Damage.

Damage stated to have been caused through vessel striking Quay Wall at Hartlepool on the 18th July 1917.

On examination whilst the vessel was loading at Hartlepool found the vessel had sustained the following damage:-

Starboard Bow. Stem bent. No. 1 Fore deck sheerstrake plate + No. 1 plate in 1st + 2nd strakes below fractured + small top stem plate started from woodwork, moulding started broken. No. 1 frame from stem fractured.

Port Bow. No. 1 Fore deck sheerstrake plate indented + No. 1 plate in 1st + 2nd strakes below fractured + moulding broken. Hawse pipe fractured in way of inside joint.

A cement box had been fitted in way of the damage from the stem to No. 1 frame as a

SUMMARY OF DAMAGE REPAIRS:-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Removed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dihng. Plates under Bounding Pipes	Copper, or T.M. of Wood Vessels
Docks	Inner Bottom Plating	Engine Room Skylights	(State if on Pelt.)
Caulking of Docks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested.	Scuppers	
Coamings	Bulkheads	Cargo Hatchways	
Beams & Fastenings	Ceiling	Hatches	
Outside Plating	Cement or Asphalt (State which.)	Plates of Wood Vessels	
Gauking of ditto	Rubber	Caulking	
Rivets	Hoisting gear and its connections	Treecalls	
Breasthooks & Crutches	Windlass	Breasthooks & Stanchions	
Transoms	Have Pumps now been examined and found effi-	Transoms, Pointers, & Crutches	
Frames	cient?	Timbers of Frame at openings	
Reverse Frames	Have Shuts Valves now been examined and found effi-	Ditto ditto at other places	
Floors	cient?	Stringers, Clamps & Shells	
Kelsons	Have Watertight Doors now been examined and found effi-	Salting	
	cient?	(State if examined.)	
			Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and p1011, &c."

This vessel is eligible in my opinion to remain as classed, subject to permanent repairs to bow being carried out on the vessel's return from the present voyage.

Survey Fee (per Section 99) £ 2 : 2 : 0
 Special Damage or Repair Fee (if any) (per Sec. 99) £ 2 : 2 : 0
 Travelling Expenses (if chargeable) £ 1 : 1 : 1
 Second Surveyor's Fee (if any) £ 1 : 1 : 1

Fee applied for.
 25 JUL 1917
 Received by me,
 26 JUL 1917

Arthur Scullard.
 Surveyor to Lloyd's Register of Shipping.

TUE OCT - 9 1917.

Committee's Minute

Character Assigned

With Mr. L. W. S. Subject



© 2018

Lloyd's Register Foundation

Temporary repair, this was found satisfactory. As the owners were anxious that the vessel should not be delayed this time, it was recommended that the permanent repairs to the bow should be carried out on the vessel, return from the present voyage.

As.

³⁶—If this Report is copied by *Captain Price*, especially now that the writing paper is so much damaged as to exceed this limit, we can assume it to allow him to do so.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:

ANCHORS

• When a bowline anchor is supplied it must be clearly stated whether it is a lot, short or full.

CHAIN CARRIERS