

25 JAN 1928

No. 191059

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 3rd January 28 when handed in at Local Office.

No. in Survey held at Hamburg

Port of Hamburg

35690 on the Hull, Iron S.C. 3 Mts. Lr. * STETTIN

Date, First Survey 21st January Last Survey 22nd January 1928

TONNAGE
GROSS 876
UNDER DE 857
NET 528.Built at Glasgow. By whom Barclay, Curle & Co. When 1864 11.
Owners Hull, Hull & Hove S.P. Co. Ltd. Owners' Address
Managers J. Currie & Co. Port belonging to Leith

Surveyed Afloat or in Dry Dock? afloat Name of Dock harbour Destined Voyage Leith

WB=CellDBorDBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.Particulars of Classification (which must be inserted
precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides
of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing,
girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 17291 Port Lth.

CHARACTER, Or for Special Surveys, Date of Survey and of Periodical Survey.	Periodical Survey Date.	Machinery and Dishes Survey Completed date of 1st. May.
+ A 1.	L.M.C. 11.24.	
6.27	+ N.B. 11.24.	
SS.LTH. 5th No. 5-11.24.	T.S. 1st May.	
	4689	
	N.D.B. 14	

(Periodical Surveys, when held, must be reported in detail and separately in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarized in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified ✓ R. ✓ inc.

Certificate attached!

Was a damage report made by anyone else? If so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition afloat after collision & temporary damage repairs:

The vessel surveyed afloat, found decks, hatchways, hatches, ventilators & coamings on deck satisfactory, steering gear & connections also windlass examined, found in good working order.

Damage found: Damage stated to have been sustained through collision with the S.S. "Astrid" in the harbour at Hamburg on the 20th January 1928.

Examination found the stem plates in sheer shake and first shake above & below sheer shake on starbd side more or less indented. 2 frames in way of these plates bent, starbd. hawse pipe broken and the anchor head of the starbd. anchor slightly damaged.

Temporary damage repairs now done: An efficient cement box has now been fitted in way of the broken hawse pipe and indented stem plates. Examined temporary repair on completion.

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates	Frames	2. Frames	Floors	Beams	Str. Plates	Dk. Plates	Other Items	R.T.O.
Removed									
Kept and Fairing or Repaired									
Faired or Repaired in place									

PRESENT CONDITION OF THE

Decks	good.	State of Tanks have been examined inside forepeak	DNag. Plates under Bowring Pipes	✓	Copper, or T.M. of Wood Vessels	
Caulking of Decks	*	State of Tanks now tested	Engines Room Skylights	good	(State of each Part)	
Coatings	*	Decks	Coal Bunkers, Open'gs, Lids, &c.	"	When put on, North	Year
Beams & Fastenings	v	Ceilings	Brackets	"	Boats	good
Outside Plating	See Report	Concrete or Asphalt	Cargo Hatchways	"	Masts, Yards, &c.	"
Breasthooks	good	Ladders	Hatches	"	Condition, how maintained	poor
Transoms	v	Steering gear and its connections	Planking	of Wood Vessels	State of wedges removed	v
Frames	See Report	Windlass	Caulking	ditto	Balls	v
Reverse Frames	v	Have Pumps now been examined and found effi-	Timbers	ditto	Equipment letter	v
Longitudinals	v	cient?	Breasthooks & Stems	ditto	Anchors, No. of	3 B. 15. 1 K.
Transverses	v	Have Valve Seats now been examined and found effi-	Timbers of Frame at openings	ditto	Gables (State of main uprights)	all
Floors	v	cient?	Timbers of frame at openings	ditto	" length	on board
Zelcons	v	Have Watertight Doors now been examined and found effi-	Doors ditto another place ditto	ditto	" width	on board
Stringers	where seen good	cient?	Stringers, Clamps & Shells	ditto	Boiler & Warps	good
Inner Bottom Plating	v	Have Ventilators and their Coatings been examined	Sailing	ditto	Standing and Running Rigging	good
		and found efficient?	(State if examined.)			

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example—“to remain as now classed in the Register Book with or fresh record of Survey,” “to remain as classed and to have record of survey 1.24,” or “to remain as classed and to have record of survey, 1.24, and the notations of No. 1-24 and 17291, &c.”

This vessel appears, as far as seen, to be in a sound & efficient condition, eligible in my opinion to remain as now classed in the Society's Register Book without fresh record of Survey, subject to damaged hawse pipe and stem plating on starbd. side being repaired on arrival at Leith.

See also 1st report No. 17291

Survey Fee (per Section 6b)	£	1	1	Fee applied for,	23 1-1928
Special Damage or Repair Fee (if any) (per Sec. 8b)	£	3	-	Received by me,	
Travelling Expenses (if chargeable) Drawing fee £	£	2	5		
Speed Surveyor's Fee (if any)	£				

Committee's Minute

FRI. 8 FEB 1928

TUES. 20 MAR 1928

Character Assigned

Deferred for April

Friedrich Ohlzen

Surveyor to Lloyd's Register of Shipping.



© 2018

Lloyd's Register
Foundation

and found same carried out in good order.
It was recommended that permanent repairs should be carried out at Keitl,
where the vessel is proceeding to.
The Surveyors at Keitl have been advised by letter.
Note: Nothing has been done at this time to itunes as per spec R. Keitl. Dr. Olyen.

The Surveyors at Ruth have been advised by letter.

Note: Nothing has been done at this time to itunes as per spec'd. List. Dr. Ohlyen.

Report No. 2—This Report is issued by Gwydir Press, special care must be taken that the original sheet is not so much handled as to spread the ink, or to cause it to adhere to the other side.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

2 When a border anchor is specified it must be clearly stated whether it is an Int., West, or East border.

CHAIN CABLES.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.