

Report of Survey for Repairs, &c., of Engines & Boilers.

No. 843	Date of Writing Report	13 th June 1890	Port of Hong Kong	(Received at London Office.)	WED 30 JULY 1890
No. in Reg. Book.	Survey held at	Hong Kong	Date, first Survey	10 th June	Last Survey 13 th June 1890
983	on the Machinery of the	<u>Strathleven</u>	Master	Berwick	No. of Visits 2
Gross tonnage	2436	Vessel built at	Pt Glasgow	By whom	Blackwood & Gordon When 1875
Net	1588	Engines made at	Pt Glasgow	When 1875	Boilers, when made (Main) (Donkey)
Registered Horse Power	220	Owners	Burrell & Sons	Port	Glasgow Voyage Europe China and Japan
No. of Main Boilers	2	If Surveyed Afloat or in Dry Dock	(State name of Dock.)	Class of Vessel & Machinery	100 A1
steam Pressure in Main Boilers	70	last Survey No.	Port	(As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.)	8, 87
in Donkey Boiler	-				

Insert Character of Ship and Machinery precisely as in the Register Book

Particulars of Examination and Repairs (if any) Thrust and Tunnel Shafting Survey.

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time?

This was not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

so what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler?

The vessel having stranded in the Saigon River on the 10th February last, being laden with a full cargo of Coals. On the vessel getting off she sank the Thrust bearing and Tunnel bearing were found to work hot, and continued to work warm while under weigh.

The caps being taken off the different bearings carefully examined shafting and found indications of the different bearings having been working hot, and the cause I consider arising from the straining of the vessel while on the ground. Recommended the Thrust and Tunnel shafting Coupling bolts be taken out and relined up.

The Thrust shaft and intermediate length of shaft, near the Thrust, are disconnected and found to be slightly out of line. The bearings of these shafts were relined up and shafting connected.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1/50, B. & M.S. 1/50, or L.M.C. 1/50, as the case may be.)

Fee or Registration Fee (per Sec. 27)..... \$3 56
Survey Fee (per Section 28)..... \$1.25-
Total Damage Fee (per Section 28)..... \$: :
Certificate (if required) as per margin..... \$: :
Selling Expenses (if chargeable)..... \$: :

Fees applied for
13.6 18 90
received by me,
25.6 18 90

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

TUE 23 DEC 90

Committee's Minute

FRI 12 DECEMBER

signed

As now

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

I do acknowledge that this document
is eligible to remain
as classified.
- M.A.
30.7.90

LR-FAC-SM9-65

© 2018



Lloyd's Register
Foundation