

112

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

No.	Date of Writing Report.	Sept-15 th 1894 Port of Yokohama
No. in Reg. Book.	Survey held at Yokohama,	Date, first Survey Sept-6 th - Last Survey Sept. 14 th 1894
994	on the Machinery of the British Steamer "Strathleven"	Master R. Cormick. No. of Visits 3
73811	Gross 2436	YEAR MONTH
Tonnage	Net 2257	Vessel built at Port Glasgow by whom Blackwood & Gordon When 1895. 11.
Registered Horse Power	220	Engines not fitted in 1889 by A. J. Suttles Glasgow
No. of Main Boilers	Two	Boilers, Chemmade (Main) 1889 (Donkey) 1884
Steam Pressure in Main Boilers	160 lbs	Owners Messrs Burriel & Son Port Glasgow Voyage New York.
in Donkey Boiler	54 lbs	If Surveyed Afloat or in Dry Dock Afloat
(State name of Dock.)		Class of Vessel & Machinery + 100A1 (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) 9.92 8396543-10.89
Last Survey No.	Port	+ NB. 10.89 LMC. 10.89.

Particulars of Examination and Repairs (if any)

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs, Repairs due to other causes. State also the dates and initials of any letters respecting this case)

id the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes, Carefully & Separately examined

Do. " Donkey " "

Yes, Carefully examined

this was not done, state for what reasons?

id what parts of the Boilers could not be thus thoroughly examined?

so what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

1 the Surveyor examine the Safety Valves of the Main Boiler? Yes, each valve seat, spring &c examined.

what pressure were they afterwards adjusted under steam? Adjusted under steam to blow off at 165 lbs.

the Surveyor examine the Safety Valves of Donkey Boiler? Yes, both valves, seats &c examined.

what pressure were they afterwards adjusted? The valves lifted under steam at 54 lbs.

All parts of main & donkey boilers were accessible.

Adjusted under steam to blow off at 165 lbs.

The valves lifted under steam at 54 lbs.

The above British Steamer "Strathleven" arrived at Yokohama August 23rd when her charter with the Japanese Yusen Kaisha for two months expired.

Special Survey Machinery and Boilers.

Repairs. All necessary parts of machinery opened out for inspection and found in good condition, the following overhauls and repairs, being then effected.

Main bearings, Crank pins, Thrust and journal bearings & crossheads overhauled & examined throughout. Thrust collars were lined up.

Cylinders, pistons, springs &c, slide valves, faces & all valve gearing examined. Low Press. slide valve refitted on spindle. Guides & piston rods examined, & one new cross-head bearing fitted.

General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification and notation of the vessel's machinery in the Register Book, consequent upon this survey; thus, for example, B.S. 1.91, B.C.M.S. 1.91, or L.M.C. 1.91, as the case may be.)

Recommendations made by me were carried out to my satisfaction & the requirements of the Society's Rules fulfilled. I recommend that the record LMC. 9.94. be made in the Register Book the case of this vessel & a certificate be granted.

Registration Fee (per Sec. 27)

£ 1 . 0 .

Fees applied for

Sept. 15 1894

to (per Section 28)

£ 2 . 0 .

\$ 96.00

Damage Fee (per Section 28)

£ 2 . 0 .

Received by me,

Expenses (if chargeable)

£ 0 . 0 .

18

MACHINERY CERTIFICATE

Certificate is required

WRITTEN.

Committee's Minute TUES. 23 OCT 1894

John J. Ford

ed

1894

LR-FAP-SAG-93

LR-FAP-SAG-92

LR-FAP-SAG-91

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping

SURVEYOR TO LLOYD'S REGISTER

TUES. 26 MAR 1895



Penguins contd.. Air, circulating, feed slide pumps, plunger, valves,
& seals exam'd & overh'd.

Donkey engines all connections exam'd & overh'd. A few
quantities of other small repairs so effected.

Main Boilers. Two, cylindrical multitudular, single ended, with
three Purvis ribbed furnaces in each boiler. Thoroughly cleaned
& scaled & carefully examined throughout & found them in
excellent condition & no appearance of any corrosion.
No repairs to the boilers were necessary, except a few
luffe plates, which were removed.

Safety valves thoroughly exam'd & all necessary boiler cocks
& valves overhauled.

Donkey Boiler. Vertical, cylindrical, multitudular. Thoroughly cleaned
& scaled & carefully examined throughout & found in very
fair condition.

The internal surfaces are more or less corroded especially
under the front tube plate, but not to any serious extent.
The back tube plate is slightly drawn out of line towards
the combustion chamber, in two places running horizontally
by the two top & bottom cross stays. This probably has been
caused by an accumulation of deposit at some time
between the plate & these stays, which are very close to each other.
On this occasion ^{the boiler} was clean. The tube stays are, in good
order however, do not lock up the tube plates well, nor perfectly
safe at the pressure fixed, of 54 lbs. The tube stays have bolts
in front & are screwed into the back tube plate. I am also
informed that the tubes have recently been renewed. They appear
in very good order.

Safety valves exam'd, overh'd & tested under steam, the pressure
being fixed at 54 lbs.

The Penguins & Boilers do are now in good order & safe working condition.

Attest

On board of her crew
a few small repairs were effected to
the engine

It is submitted that
this vessel is registered on
THE RECORD L.M.C. 9-93 and

B.S. 9-94.
D.P. Bureau to be
entered in the Register
Book at 54 lbs.

19.10.94
J.J.A.



© 2018

Lloyd's Register
Foundation