

FRIDAY 22 MAR 1895

(Received at London Office)

18

No. 11197

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report Mar 21st 1895 When handed in at Local Office Mar 21st 1895 Port of Greenock
 No. in Survey held at Port Glasgow Date, First Survey 5th Feb Last Survey 13th Feb 1895
 Reg. Book. 1038 on the Wood, Iron or Steel S/cr Stm Strathleven Master J. Cornack
 TONNAGE:- Built at Port Glasgow By whom Blackwood & Gordon When 1875 - 110
 GROSS 2436 Owners Burwell & Son Port belonging to Glasgow
 UNDER DR. 2257
 NET 1588 Owners' Address
 Surveyed Afloat and Name of Dock Port Glasgow Destined Voyage Alexandria for Batium.
 WB=DAa tons; f tons; uE&B tons; CellDB tons; tons;
 FPT tons; APT tons; MT tons.

N.B.—All alterations in the existing records should be underlined.
 If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 656 S/S Port Shanghai

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawser is reported, the particulars of weight or size and test of the articles will be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment if any. State also the dates and initials of any letters respecting this case.)

PAIRS, OR EXAMINATION AS PER RULE, FOR Damage stated to have been sustained
 (1) by grounding on E Coast of Japan on 26th July 1894 while on a voyage from Hakodate to Yokohama. For further particulars see damage,
 (2) through stress of weather from 12th to 16th Jan on voyage from New York to Liverpool.
 The vessel placed in dry dock, and bottom recoated after repairs were completed.

Repairs now effected.

(1) Plating: The following fractures, plates renewed. shell
 In way of Boilers: P. side— one garboard strake and three in Astokes
 S side— one garboard plate.

In way of Engines: P side. two plates in A strake; and in way of A. 2 holds
 one plate in B strake.

Plates fair'd replaced: Boiler Room—P side. one in portboard strake, two in B strake and 1 in C; S side— one in garboard and 2 in A strake: in way of spare bunkers one plate in A strake; way of C holds, one in B strake, 2 in after hold, one in A strake.

1 floor plate renew'd. 3 fair'd
 SUMMARY OF DAMAGE REPAIRS:— 10⁰ Plates, Paired or Repaired; 29⁰ Frames, ditto. 8⁰ Plates, Renewed; 16⁰ Frames, ditto. Other Repairs Small deck fittings, etc.

PRESENT CONDITION OF THE

Beams	Good.	Transoms, Pointers, & Crutches	Not seen	Copper, or T.M. (State if on Felt.)	Good	Hatches	Good
Interways	—	Plates of Frame at the openings	where seen	When put on, Month	✓ Year	Boats	—
Samings	—	Bitto, ditto at other places	seen	Rudder	Good	Masts, Yards, &c.	—
p'r Dr. Beams & Fastenings	—	Kelsons	good	Windlass & Capstan	—	Condition, how ascertained	Sound decks
ov'r Dr. Beams & Fastenings	—	Clamps, Shells & Stringers	—	Pumps	—	Sails	—
Lathing	—	Salting (State if examined.)	—	Engine Room Skylights	—	Equipment letter	—
Decking	✓	Ceiling	—	Coal Bunkers, Open'gs, Lids, &c.	—	Anchors, No. of	313 1S. 2A
Fastenings & Rivets	where all seen	Cement or Asphalt (State which.)	Good as far as seen	Scuppers	—	Cables (State if now ranged.)	Yes
Breasthooks & Stemson	Not seen	Tanks (State if now tested.)	—	Cargo & Main Hatchways	—	" length 300 size 1 1/2" G. P. f. f.	—
		Caulking of Bot'm, Dk, & Wat're'y's	Good			" Rule length 270 size 1 1/16"	—

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notation of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9.91," or "to remain as classed and to have record of survey, 9.91, and the notations of as No. 1-91 and pnd 91, &c."

This vessel is now in a good and efficient condition eligible in my opinion to remain as classed and to have record of survey 3.95 with the notation of S.S. Shi 4.9.94 now the repairs have been effected.

Office Fee (if chargeable) per Scale II, Sec. 27 £ : : :
 Survey Fee (per Section 28) £ : : :
 Special Damage or Repair Fee (if any) per Sec. 28 £ 5 : 5 : -
 Travelling Expenses (if chargeable) £ 10/- 5 : 5 : -
 Second Surveyor's Fee (if any) £ 44.114. -

*Is Certificate now required?

Committee's Minute

Character assigned

Fees applied for,

20.3.95

Received by me,

22.3.95

E.P.

23.3.95

Surveyor to Lloyd's Register of British & Foreign Shipping.

S. A. G. Marsh.

Form No. 2 for
The Surveyor is requested not to write on or below the space re-

100AI 3/95
as Nat-94

No. 1-94

Bravington 11
1895

© 2018



Lloyd's Register
Foundation

S.S. Strathleven

Repairs (continued)

Plating: Eight plates (4 S side 4 P) slightly unsafe, now faires in place, viz., P side - 2 garboards plates, one plate in B stroke, 2 in C stroke; S side - 2 garboards plates and 2 in C stroke.

Floor plates. P side - one renewed at m.l. for about 8 ft. 8 1/2 faires in

Frames: In way of Boiler room - 11 frames on P side and five on S side renewed from m.l. to bilge in lengths of about 14 ft 4 1/2 ft alternately; one short length renewed;

and 2 frames on P side and 6 on S side faires in place after cutting out the frame rivets. In way of No 2 holes, spare bunker engine room - 21 frames fived and faires.

Some stinkles frame rivets and the lugs to side intercostal keelson in engine room renewed. Twelve m.l. heel pieces to new frames renewed, and 3 faires and riveted, and the angle lugs or chocks to the side and bilge keelsons renewed in way of the faires and renewed plating.

Cement in way of damaged plating renewed, and all work disturbed to effect the foregoing repairs, as boiler room platform, spar and close ceiling replaced or made good where damaged.

(2) Damage through stress of weather.

Forecastle winghouse, & bulkheads of bridge front and all gangway on P side repaired, wood cover to steam pipe and iron plate covers to steam pipes renewed where broken; four lengths of waterservice pipe repaired and connections made good; port lifeboat repaired and steering gear overhauled; door to No 2 gangway and one bulwark plate set fair, 8 ft of rail angle & wood straights renewed, S bulwark stanchions riveted, and other small repairs effected.

S. A. T. Nash.