

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 25/3/1898 When handed in at Local Office 25/3/1898 Port of Glasgow

No. in Survey held at Glasgow Date, First Survey 4 August 1897 Last Survey 24 March 1898  
Reg. Book. 848 on the Wood, Iron or Steel Sc. 4 Mot. St. Arizona (No. of Visits) 50. Master J. Pantou 1898

TONNAGE: - Built at Glasgow By whom J. Elden & Co. When 1879-3  
GROSS 5305 Owners Guion S.S. Co. (Limited) Port belonging to London  
UNDER DK. 5004  
NET 3356 Owners' Address

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Govan Destined Voyage Pacific

WB = Cell D Bord Ba feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted  
total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements).

N.B. - All alterations in the existing records should be underlined.  
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 410726 Port Liverpool

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR S.S. No 3 and alterations

Vessel placed in dry dock. Holds, peaks and bunkers cleared. Engines and boilers taken out. All close ceiling and sparring removed in holds and tween decks. Cabins, Saloons & fitted out. Linings in same removed. All oxidation removed from the surfaces of plating, frames & throughout and the iron work recoated. Current everywhere examined & found to be in good condition & closely adhering to the iron. Masts taken out. Chain cables roused, pumps, watertight doors & overhauled.  
Repairs now done. In fore peak, 2 reverse frames repaired. In No 1 hold, the parting beams which were found to be adrift have been replaced with 3 - 11 inch bulk beams together with an additional stringer plate and gusset plates on each side. A broken beam knee doubled and a reverse frame renewed in lower tween decks. Chain pipes repaired. In No 2 hold, all orlop beams removed and replaced with a strong beam - face angles to stringers and large gusset plates at beam and bulkheads as shown on approved plans attached hereto. Hatchways luffboard 4/8 and web plate

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed ... ..								
Paired or Repaired ...								

PRESENT CONDITION OF THE	Timbers of Frame at the openings	Rudder	Hatches
Decks <i>Good</i>	<i>Good</i>	<i>Good</i>	<i>Good</i>
Waterways	Keelsons	Windlass & Capstan	Boats
Coamings	Stringers, Clamps & Shells	Have Pumps now been examined and found efficient? <i>Yes</i>	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings	Saltings (State if examined.)	Have Sluice Valves now been examined and found efficient? <i>Yes</i>	Condition, how ascertained. <i>By examination</i> (State if wedges removed <i>Yes</i> )
Low'r Dk. Beams & Fastenings	Ceiling	Have Watertight Doors now been examined and found efficient? <i>Yes</i>	Sails <i>Good</i>
Plating	Cement or <i>Asph</i> (State which.)	Dblng. Plates under Sounding Pipes <i>Good</i>	Equipment letter <i>at</i>
Planking	Tanks (State if now tested.)	Engine Room Skylights	Anchors, No. of <i>4 B. 15. 1K</i>
Rivets or <i>Seconals</i>	Caulking of Bot'm, Dk, & Wat'r'ys	Coal Bunker, Open'gs, Lids, &c.	Cables (State if now ranged) <i>Yes</i>
Breasthooks & Stemson	Copper, on Y.M. (State if on Feit.)	Scuppers	.. length <i>300'</i> size <i>2 3/8"</i> (on board)
Transoms, Pointers, & Crutches	When put on, Month <i>Feb.</i>	Cargo & Main H'tch'ys	.. Rule length <i>240'</i> size <i>2 5/8"</i> (per Table 25)
			Hawsers & Warps <i>Good</i>
			Standing & Running Rigging <i>du</i>

### General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,97," or "to remain as classed and to have record of survey, 1,97, and the notations of ss No. 1-97 and pND97, &c."

This vessel is now in a good and efficient condition and the Rules for 3<sup>rd</sup> Special Survey having been complied with she is eligible in our opinion to remain as classed with record of survey No. 3.98 and the notation S.S. No. 3. 3.98 also amended record of tonnage as above.

Office Fee (if chargeable) per Scale II., Sec. 27	Survey Fee (per Section 28)	Special Damage or Repair Fee (if any) (per Sec. 28.)	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)	Fees applied for.	Received by me.
£	10	1	9	£	2. 14 1898	<i>Not</i>
						<i>14 18</i>

Committee's Minute TUES. 5 APR 1898

Character assigned 100 A1

S.S. No. 3. 3.98  
L.M.C. 3.98. - N.B. 3.98

Yes  
Has a Survey also been held on the vessel by the Ship? If so, in the Report sent now, or when will it be sent?

GLASGOW.

Certificate required? To be sent to

MON 4 APL 1898

Port of Glasgow

Continuation of Report No. 15947 dated 24 March 1898

S.S.

"Arizona"

Supporting beams fitted to same at each hatch deck. In No 3 hold all orlop beams removed and compensated in the same manner as at No 2 hold and as shown on approved sketch. A screen bulkhead renewed in lower tween decks. No repairs to No 4 hold and steel hatch coaming fitted to main deck in No 5 hold.

In Boiler space - 40 floors, which were found somewhat wasted near the middle line, have been doubled from side keelson to side keelson on each side. The bottom angle bars to side keelsons renewed on each side, all the angles of bilge keelson on port side and the lower angles to bilge keelson on starboard side renewed. Rider plate to centre keelson renewed and rider plates fitted to bilge keelsons and bilge stringers throughout boiler space. The foundation plate to middle line keelson stiffened with angles  $5 \times 4 \times \frac{5}{8}$  on its upper outer edges. The angle and face plates to 4 web frames in boiler and bunker space renewed and rider face plates fitted to all the other web frame in those spaces.

The pocket bunkers rebuilt - Two plates renewed in transverse watertight bulkhead at after end of boiler space.

Two orlop deck beams renewed in boiler hold and one additional beam fitted. Two stringers of lower deck plating renewed in lower tween deck bunker and 6 plates renewed at middle of deck.

Fore boiler hatchway in upper, main and lower decks filled in with carlings and plated over; the number of loadens carried in the vessel having been reduced.

An outer plate renewed on each side of stern, 12 outside butt straps fitted over wasted butts of bilge plating on starboard side and 11 on the Port side. Coamings to hatchways and boiler coaming on upper deck doubled where necessary and repaired.

Cargo doors fitted in tween decks - as shown on attached sketch. Upper deck renewed with 3" Teak. Promenade deck renewed with  $\frac{3}{4}$ " Yellow Pine. A part of flat of main deck renewed. All stove ceiling and sparring renewed in holds and tween decks. Additional pillars fitted in tween decks where previously omitted on account of saloon &c. All hatches and fore and afters to hatchways renewed. Masts replaced & vessel rigged.

In consequence of the excellent condition of the shell plating it was not considered necessary to ascertain its thickness by boring.

J. Hearley  
J. Dodd