

COPY.

G.O.

Lloyd's Register of Shipping.



Port Copenhagen

Class Contemp^d 18th March, 1935.

This is to Certify that

S. Sandersen

the undersigned Surveyor to this Society did at the request of H. Rask Petersen, Esq., Lloyd's Agent, Odense, and with the consent of Messrs. Odense Staalskibsværft A/S, Odense, on the 25th January 1935 and subsequent dates survey the m.s. "PERNA", (yard newbuilding No. 54) without prejudice to the various interests concerned, while the vessel was afloat alongside the yards outfitting quay for the purpose of ascertaining the nature and extent of damage stated to have been sustained through fire onboard on the 24th January, 1935.

On examination the undersigned

Found:-

, Recommended:-

Saloon house:-

5 sidelights of metal with dead- To be renewed.
lights and glasses in way of
saloon damaged.

3 glasses for sidelights and 2 To be renewed.
fixed glassed in skylight broken.

" Dermas " deck covering in way of To be renewed.
saloon damaged by water and heat.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
" While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

003659-003670-0134 15

© 2020
Lloyd's Register
Foundation

Found:-

Recommended:-

O.P. wood deck in port passage and in part of the cabins in way damaged by fire.

To be renewed.

O.P. wood deck in starboard passage damaged by water and smoke.

To be planed and recaulked.

Wood bulkheads, wood linings etc. partly damaged by fire, smoke or water.

To be renewed where damaged.

Panels, furniture etc. in saloon and cabins etc. partly damaged by fire, smoke or water.

To be renewed or cleaned and repolished as necessary.

10 plywood doors and 1 teak door with frames damaged by fire and water.

To be renewed.

Ice chest in pantry damaged by smoke and water.

To be repaired, mountings to be replated and chest to be repainted.

Hot press in pantry damaged by smoke and water.

Top part to be renewed.

Metal screen for radiator in saloon damaged by fire.

To be renewed.


Boat deck:-

9 deck beams buckled.

To be renewed.

Tie plates in way buckled.

To be renewed.



© 2020

Lloyd's Register Foundation

0134 215

Found:-

Recommended:-

Deck plates in front of
Captain's house buckled.

To be renewed.

Foundation angle bars in
way of deck house and front
bulwark set down.

To be taken out, faired and
replaced.

P. wood deck outside the
Captain's house partly damaged
by fire.

To be renewed where damaged.

P. wood deck inside the
Captain's house damaged by
fire.

To be renewed.

Files and cement in Captain's
bathroom etc. damaged by heat
and water.

To be renewed.

Captain's house:-

front plates buckled due
to beam having sagged.

To be taken out, faired and
replaced.

front plates in way slightly
buckled.

To be faired in place.

polished hard wood doors
damaged by smoke and water.

To be renewed.

teak doors with frames
damaged by smoke.

To be cleaned and revarnished.

wood bulkheads, linings etc.
partly damaged by smoke and
water.

To be renewed where damaged.



© 2020

Lloyd's Register
Foundation

0134 15

Found:-

Recommended:-

Panels, furniture etc. damaged by smoke and water.

To be renewed or cleaned and repolished as necessary.

Chart- & wheel house:-

Furniture damaged by smoke.

To be cleaned and repolished.

Wood lining and doors damaged by smoke.

To be cleaned and revarnished.

Electric installation:-

Cables, switches, fuse boxes, fittings etc. in way of midships accommodation partly damaged by fire and water.

To be fully renewed.

Panels with instruments, boxes etc. partly damaged by smoke and water.

To be taken down, overhauled and renewed as necessary and tested after repairs.

Sanitary installation:-

Pipes with fittings partly damaged by fire.

All pipes with fittings in way of the midships accommodation to be overhauled and renewed where necessary and tested after repair.

Fittings for baths, wash basins etc. damaged by smoke.

To be cleaned, overhauled and replated where necessary.

6 wash basins damaged by heat and smoke.

To be renewed.



© 2020

Lloyd's Register
Foundation

0134 4/5

Found:-Recommended:-Telemotor- & telegraph lines:-

Pipes with fittings, rods, chains, wheels etc. partly damaged by fire and water.

To be taken adrift, examined, renewed where damaged and tested after being refitted.

Telemotor, telegraph and compass house in the wheel house partly damaged by smoke.

To be cleaned, examined, adjusted and repolished.

Heating arrangement:-

Radiators with fittings partly damaged by heat and water.

To be taken down, renewed or repacked where damaged and tested.

Pipes with fittings etc. partly damaged by heat and water.

To be overhauled, renewed where damaged and retested.

Painting:-

Painting of houses, accommodation, decks etc. (inside and outside) partly damaged by heat or smoke.

To be cleaned, scraped off where necessary and repainted to the same extend as before the damage was sustained.

Further recommended that all necessary removals be replaced, and (where damaged in course of above repairs) repaired or renewed as necessary, the repairs suitably coated on completion of work.

These recommendations made so as to place the vessel in the same condition as before the damage was sustained.

Fees:- 345,00 Kr.

Expenses:- 150,00 Kr.



S. Sanderson
© 2020
SURVEYOR TO LLOYD'S
REGISTERED

Lloyd's Register
Foundation

0134 5/15

Expenses:- 150,00 Kr.
Fees:- 345,00 Kr.

2020

Lloyd's Register
Foundation

In the same condition as before the damage was sustained.
These recommendations made so as to place the vessel
on completion of work.

Repaired or renewed as necessary, the repairs suitably coated
be replaced, and (where damaged in course of above repairs)

Further recommended that all necessary removals
smoke.
the damage was sustained.

alids) partly damaged by heat or to the same extent as before
tion, decks etc. (inside and out-where necessary and repainted

Painting:- To be cleaned, scraped off
To be cleaned, scraped off

ly damaged by heat and water. damaged and retested.

pipes with fittings etc. partly- To be overhauled, renewed where
fested.

ly damaged by heat and water. repacked where damaged and
To be taken down, renewed or

Radiators with fittings partly-
Heating arrangements:-
house partly damaged by smoke.

compass house in the wheel
Justed and repolished.

Telemotor, telegraph and
To be cleaned, examined, ad-
damaged by fire and water. after being refitted.

chains, wheels etc. partly renewed where damaged and fasted
pipes with fittings, rods, To be taken apart, examined,

Telemotor & telegraph lines:-

Found:-

Recommended:-

57