

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN
AUXILIARY
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)	AUXILIARY
Total kW or kVA	Total kW or kVA
a Generators	l Generators & governors
b Exciters	m Motors
c Air coolers	n Switchboards & fittings
d Motors	o Circuit breakers
e Air coolers	p Cables
f Control gear cables, etc.	q Insulation resistance
g Insulation resistance	r Steering gear generators & motors
h Insulating oil test	s Navigation light indicators
i Overspeed governors	
j Magnetic couplings	
k Air gap	

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

Starboard Boiler:

Found 5 wrapper plate stays of port combustion chamber badly necked. These stays satisfactorily renewed. The newly fitted stays have been made of approved material.

Superheater Elements:

Satisfactorily repaired and partly new superheater elements have been re-fitted this time in Port, Centre & Starboard boilers.

Owners state that superheater elements in forward boiler will not be re-fitted.


It is recommended that the notation in the Register book regarding the boilers accordingly be amended.

Screwshaft Survey:

Wear down of stern bush 0.210 inch. Found lignum vitae moved outwards approx. 2" due to failure of the check ring bolts.

..... contd...

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



© 2021

Lloyd's Register
Foundation

Ship's Name SS/MS "SAFINA-E-JAMHOORIYAT"
LR 530490

Port Karachi

Rpt. No.

KRH/801


Now done:

Shaft drawn and examined together with sternbush and tube. Found good. Lignum Vitae and check ring bolts renewed. Shafts and propeller satisfactorily re-fitted.

S.R.L. No.234:

4 seal welded stay tubes in centre tube nest of Starboard boiler satisfactorily renewed.

It is recommended that the condition of class relating to these tubes be deleted.


SURVEYOR TO
LLOYD'S REGISTER OF SHIPPING.



© 2021

Lloyd's Register
Foundation