

Class is subject to New propeller being fitted at the next dry docking.

4E

27 JUL 1962

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME.....

"NAGUSENA"

REPORT

Rot

No. 54156

Docking screwshaft examined found cracked on top of cone and now replaced by a new shaft.

MBS due 9.62 now held.

Machinery repairs stated due to heavy weather damage, thrust shaft found cracked at after coupling and now renewed, crankshaft journals found slack in way of shrink fits and screwshaft removed ashore and rebuilt with new journals and pins all bearings rematalled and shaft alignment verified on completion.

SRL item: ~~the~~ new cast iron propeller now fitted and this item may be deleted.

IT IS SUBMITTED that this vessel is eligible to have the record of MBS 5.62 TSCL 4.62 N. without subject.



© 2020

27.7.62

Lloyd's Register
Foundation