



with their mountings, superheaters, doors fastenings and found or placed in satisfactory condition. Afterwards examined under steam and their safety valves adjusted to 500/473 lb. The oil-burning installation and fire extinguishing arrangements checked.

### Repairs.

Alternator rotor shaft journals skimmed and the bearings re-metalled.

Main motor cooler removed for investigation of leakage. 2 tubes and some header bolts renewed.

New impeller & shaft fitted to main circulating pump.

New impeller shaft to auxil. circulating pump.

Inbid aux. turbine rotor skimmed in way of packing.

One diaphragm built up in main turbine where faces were

After boiler feed pump rotor renewed (old one bent).

The main injection valve chest built up with etc. or fitted with doubler patch, at local areas of deep wear.

A number of tubes renewed in the main condenser.

### Electric Propelling Machinery

All the electric propelling machinery comprising, alternator, motor, exciter, control gear etc opened up for survey. All parts checked, windings cleaned & gears overhauled, slip rings & commutator ground, brush gear overhauled. Insulation test on Equipment tested under full working conditions at sea & found satisfactory.

### Auxiliary Electrical Equipment.

Installation examined & tested. All motor & control gear opened up, switches, transformers, generator, wiring etc examined & tested. All found satisfactory.

Repair:- Generator overhauled & cleaned commutator skimmed, all motor overhauled & made good, a number of new bearings fitted. Wiring throughout vessel overhauled faults made good. Low insulation faults located & removed.

Noted

JM

2/9/52



© 2020  
Lloyd's Register  
Foundation