

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

JUN -3 1940

Date of writing Report 8/4/ 1940. When handed in at Local Office 10th Apr. 1940 Port of Kobe.

No. in Reg. Book. 33372 Survey held at Osaka. Date, First Survey 22/3/40. Last Survey 2/4/1940. (No. of Visits Four.)

33372 on the Machinery of the ~~Wood, Iron or Steel~~ S/S "SEIAN MARU"

Tonnage { Gross 1900
Net 1054 Vessel built at Leith. By whom Ramage & Ferguson, Ltd. When 1911 6mo.

Nominal Horse Power { 264 NHP Engines made at Leith. By whom Ramage & Ferguson, Ltd. When 1911

No. of Main Boilers 2 SB Boilers, when made (Main) 1911 (Donkey) --

No. of Donkey Boilers -- Owners Sakamoto Shoji Kabushiki Kaisha Owners' Address (if not already recorded in Appendix to Register Book.)

Steam Pressure 180 lbs in Main Boilers -- Managers Osaka. Port Osaka. Voyage --

in Donkey Boilers -- If Surveyed Afloat or in Dry Dock Both Fujinagata Dock.

Last Report No. PortParticulars of Examination and Repairs (if any) LMC

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined --

Was a damage report made by anyone else? If so, by whom? --

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes.

" " Donkey " " " --

If this was not done, state for what reasons? --

And what parts of the Boilers could not be thus thoroughly examined? --

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? --

State latest date of internal examination of each boiler March 1940.

Present condition of funnel(s) Good

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes.

To what pressure were they afterwards adjusted under steam? 180 lbs.

Did the Surveyor examine the Safety Valves of Donkey Boiler? --

To what pressure were they afterwards adjusted under steam? --

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes.

, and of the Donkey Boilers? --

Did the Surveyor examine the drain plugs of the Main Boilers? --

, and of the Donkey Boiler? --

Did the Surveyor examine all the mountings of the Main Boilers? Yes.

, and of the Donkey Boiler? --

Has screw shaft now been drawn and examined? No

Is it fitted with continuous liner? --

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? --

Has shaft now been changed? -- If so, state reasons --

Has the shaft now fitted been previously used? --

Has it a continuous liner? --

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? --

State date of examination of Screw Shaft --

State the distance between lignum vitae or bearing-metal of stern bush and top of after bearing of screw shaft 3/16".

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light ~~and of power~~ fitted? Yes.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

NOW DONE:- Vessel placed in dry dock, propeller, aft end of stern bush, sea cocks and valves with their shell fastenings examined and found or now placed in good condition.

All cylinders, pistons, valves and rods, crank, thrust and intermediate shafting, condenser, pumps, piping and pumping arrangements examined and found or now placed in good condition.

The 2 Main Boilers were examined over all parts with doors, mountings and safety valves and found or now placed in good condition. Safety valves adjusted under steam as stated above.

REPAIRS DUE TO WEAR AND TEAR:-

H.P. cylinder liner skimmed up and new packing ring fitted.

H.P. crosshead pin - renewed.

10 small stays and 2 plain tubes in boilers - renewed.

Other minor repairs and adjustments effected.

General Observations, Opinion, and Recommendation:—The machinery and boilers of this vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.M.S. 9,11, & L.M.C. 9,11, or

are in good condition and eligible, in my opinion, to be continued as classed with fresh record of

L.M.C. 4, 40.

Survey Fee (per Section 29) Yen 190;00

Fees applied for 2/4/ 1940

Special Damage or Repair Fee (if any) £ -- : -- :

(per Section 29.)

(See Hull Report).

Travelling expenses (if chargeable) £ -- : -- :

Received by me, 19


Committee's Minute

TUE 11 JUN 1940

Assigned 4.40

CERTIFICATE WRITTEN

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

007506 - 007517 - 0295