

## REPORT OF SURVEY FOR REPAIRS, &amp;c., OF ENGINES AND BOILERS

(Received at London Office)

4-JAN-1954

Date of writing Report 14<sup>th</sup> Dec 53 When handed in at Local Office 28.12 53 Port of Marseilles  
 No in Reg. Book Survey held at Marseilles Date First Survey 26<sup>th</sup> November Last Survey 5<sup>th</sup> December 1953  
 (No. of Visits SEVEN)

na146 on the Machinery of the Welded Steel Screw Turb Tanker "ESSO BRETAGNE"  
 Gross 10648 Vessel built at Portland Oregon By whom Kamco Inc When 1944  
 Net 6301 Engines made at Lynn Mass By whom General Steam Co When 1944  
 Nominal 1436 Boilers, when made (Main) 1944 (Donkey) ✓  
 Power 1436 Owners Esso Ind Soc Am Fr Owners' Address (if not already recorded in Appendix to Register Book.)  
 of Main Boilers 2 Managers Port Havre Voyage  
 of Donkey Boilers ✓ If Surveyed Afloat or in Dry Dock Both  
 Pressure 500 (state name of Dock.)  
 Main Boilers 500  
 Donkey Boilers ✓

## Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER * for Special Survey. Date of last Survey and of Periodical Surveys.	Years assigned new expired.	Machinery and Boiler Surveys (including date of N.B., if any)
<u>100 A 1</u>	<u>2.53</u>	<u>LMC 253</u>
<u>Classed 3-49</u>		<u>TS CL 14.52</u>
<u>SS 174 3-48</u>		
<u>Carrying Petroleum in Bulk</u>		
<u>Fitted for oil fuel 7P above 150°F</u>		

Insert Character of Ship and Machinery precisely as in the Register Book.

Particulars of Examination and Repairs (if any) T.S. - BS & Machinery Repairs  
 Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides, be detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and details of any letters respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Has a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a through examination at this time? yes

Did the Surveyor personally go inside each Donkey Boiler separately and make a through examination at this time? yes

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

What was the latest date of internal examination of each boiler? Port & Star 26<sup>th</sup> November

Did the Surveyor examine the Safety Valves of the Main Boilers? yes To what pressure were they afterwards adjusted under steam? good

Did the Surveyor examine the Safety Valves of the Donkey Boilers? ✓ To what pressure were they afterwards adjusted under steam? not adjusted

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? yes and of the Donkey Boilers? ✓

Has the screw shaft now been drawn and examined? yes Has it a continuous liner? yes Is an approved oil retaining appliance fitted at the after end? ✓

Has the shaft now been changed? no If so, state reasons. ✓ Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓

Is an approved oil retaining appliance fitted at the after end? ✓ State date of examination of Screw Shaft. 1<sup>st</sup> December 53 State the wear down in the

tern bush. 128 Is electric light and/or power fitted? yes If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? yes

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? yes

When parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. It is stated that the safety valves of Port & Star Boilers

have been adjusted at first opportunity and that the support castings of Starboard Boiler will be replaced at first opportunity

NOW DONE a) for Docking and TS Vessel placed in dry dock Propeller, sea connections fastenings

examined. Screw shaft drawn in and examined. Lower part of stem bush rewooded

b) for Boiler Survey Port and Starboard Boilers examined internally & externally together with

man hole doors & their fastenings all mountings & fittings, superheaters and economisers.

The oil fuel and steam heating installation generally examined and tested under working condition

Repairs due to wear & tear:

Star Board Boiler Approx 195 air heater tubes replaced

One heater nipple replaced

Port Boiler Approx 195 air heater tubes replace

Whole superheater nest replaced together with its support castings

The Star Board castings supporting the split tubes nest found partly burnt off can remain in my opinion efficient up to the date recommended

for next examination.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9.11, B&MS 9.11, LMC 9.11 or LMC 140 lb., FD, &c.)

The machinery of this vessel so far as has been seen is in good condition and eligible in my opinion to remain

classified with fresh record of TS CL 12.53 and BS 11.53 when the safety valves have been adjusted

under steam, subject to the superheater's nest and its supporting castings of Starboard Main Boiler being

examined not later than the end of March 1954

Survey Fee (per Section 29) Fr 40.000

Special Damage or Repair Fee (if any) Fr 18.000

(per Section 29.) Fr 42.00

Travelling expenses (if chargeable)

Committee's Minute

Assigned

Fees applied for Fr 12.19.53

Received by me, ✓

TUESDAY 19 JAN 1954

As new subject

8.12.53

010289-010293-0235 1/2

Lloyd's Register

Foundation

© 2021

Engineer Surveyor to Lloyd's Register of Shipping.

Is a Certificate required? If so, to be sent to

4-JAN 1954

Rpt. 9a

Continuation of Report No. 11562 dated 28-12-53

Port of

ESSO BRETAGNE

## c) for Machinery Repairs

Main propelling Electric motor: 14 spools replaced

Main Turbine opened up, examined throughout. Dummies replaced

Outboard Turbo Generator Steam part &amp; reducing gear examined throughout

Inboard Turbo Generator Reducing gear and electrical part examined throughout

Main circulating pump opened up. Impeller, shaft &amp; casing examined


Fwd Turbo feed pump examined throughout steam &amp; water part

Aft Turbo feed pump. Steam part opened up &amp; examined throughout

Main Condenser opened up, cleaned and tested

Two Ballerworth heaters opened up cleaned &amp; tested 28 Kgs

Electrical circuits generally examined and satisfactorily megger tested



© 2021

Lloyd's Register  
Foundation

010289-010293-0238 2/2