



S.M. "SEDILI"

worn, slightly scored, and slightly corroded in way of bearing. Shaft was skimmed up and a new cast-iron bearing, and new gland neck ring were fitted. Vicker's Oil Gland Assembly was machined as necessary and re-fitted, with new felt and rubber rings.

All Sea Valves in Engine Room were opened up, ground in, examined, and replaced in good order.

The Propeller was in good condition.

*Done*



© 2021

Lloyd's Register Foundation

0121 2/2