

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report *10th May 1906* When handed in at Local Office *10.5.1906* Port of *Aberdeen*
 No. in Survey held at *Aberdeen* Date, First Survey *20.3.* Last Survey *3rd May 1906*
 Reg. Book. on the Wood, Iron or Steel *S.S. "Imyoni"* Master *P. J. Jackman*
 TONNAGE: Built at *Aberdeen* By whom *Hall Russell & Co* When *1892*
 GROSS *1945* Owners *P. J. Jackman & Son* Port belonging to *Aberdeen*
 UNDER DE. *1866* Owners' Address
 NET *215.9* (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? *Yes* Name of Dock *Aberdeen* Destined Voyage *London to load*

WB=CellDBorDBa feet; uE&B feet; f feet; }
 total capacity tons. FPT tons; APT tons; MT feet tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Yard	Machinery and Boiler
For Special Survey.	Amended	Survey
Date of last Survey and of Periodical Surveys.	now	(including date of N.B., if any).
<i>100. A. 1</i>	<i>LMC 7.03</i>	
<i>Span Deck</i>	<i>11.05</i>	
<i>S.S. Sur. No. 3-7.03</i>		
Society's Freeboard (if assigned) as painted on Ship and now verified		

Last Report, No. *67922* Port *Lon.*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? *✓* also whether any damage report was made, and, if so, by whom? *✓*

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Condition & repairs in connection with the*

fitting of new boilers.
Vessel placed in dry dock. Bottom & rudder cleaned & scraped, examined, & recoated. Work consequent on the fitting of new boilers as follows:
Funnel, boiler casing top & starboard side, ventilators & fiddley gratings, removed. Bridge, spar & main decks opened up on starboard side, deck plating & carling beams in way of boiler opening removed, and main beams put ashore. Boiler space cleaned out, from 4th to 9th frame inclusive, abaft storehold bulkhead, (i.e.) immediately in way of main boilers, and the following repairs to floors, reverse frames & boiler stools carried out viz. 3 floors (carrying boiler stools) fitted with doubling, & joggled.

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>
Removed and Faired or Repaired	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>
Faired or Repaired in place	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>

PRESENT CONDITION OF THE

Decks <i>Good</i>	Stringers <i>where seen good</i>	Dging. Plates under Sounding Pipes <i>not ex?</i>	Copper, or Y.M. of Wood Vessels <i>✓</i>
Caulking of Decks <i>—</i>	Inner Bottom Plating <i>not exam'd</i>	Engine Room Skylights <i>Good</i>	(State if on felt.)
Waterways <i>—</i>	State if Tanks have been examined inside <i>no</i>	Coal Bunkers, Open'gs, Lids, &c. <i>✓</i>	When put on, Month <i>Good</i>
Boamings <i>—</i>	State if Tanks now tested <i>no</i>	Scuppers <i>✓</i>	Boats <i>Good</i>
Beams & Fastenings <i>where seen good</i>	Bulkheads <i>where seen good</i>	Cargo Hatchways <i>✓</i>	Masts, Yards, &c. <i>—</i>
Outside Plating <i>Good</i>	Ceiling <i>—</i>	Hatches <i>✓</i>	Condition, how ascertained <i>from deck</i>
Caulking of ditto <i>—</i>	Cement or Asphalt (state which) <i>Good</i>	Planking of Wood Vessels <i>—</i>	(State if wedges removed) <i>no</i>
Rivets <i>—</i>	Rudder <i>Good</i>	Caulking ditto <i>—</i>	Sails <i>Reported good</i>
Breasthooks & Crutches <i>not exam'd</i>	Windlass <i>—</i>	Treenails ditto <i>—</i>	Equipment letter <i>R.</i>
Transoms <i>—</i>	Have Pumps now been examined and found efficient? <i>not exam'd</i>	Breasthooks & Stemson ditto <i>—</i>	Anchors, No. of <i>3 B. 15. 18.</i>
Frames <i>where seen good</i>	Have Sluice Valves now been examined and found efficient? <i>—</i>	Transoms, Pointers, & Crutches ditto <i>—</i>	Cables (State if now ranged) <i>yes</i>
Reverse Frames <i>—</i>	Have Watertight Doors now been examined and found efficient? <i>—</i>	Timbers of Frame at openings ditto <i>—</i>	length <i>205 fms</i> size <i>1 1/2</i>
Floors <i>—</i>		Ditto ditto at other places ditto <i>—</i>	Rule length <i>240"</i> size <i>1 1/2</i>
Keelsons <i>—</i>		Stringers, Clamps & Shells ditto <i>—</i>	(on board)
		Sinking (State if examined.) ditto <i>—</i>	Rule length <i>240"</i> size <i>1 1/2</i>
			(per Table 23)
			Hawsers & Warps <i>Good</i>
			Standing & Running Rigging <i>—</i>

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel appears to be now, in good & efficient condition, & eligible in my opinion to remain as classed, with record of survey, 5.06.

Office Fee (if chargeable) per Scale II., Sec. 27 *£*

Survey Fee (per Section 28) *£*

Special Damage or Repair Fee (if any) *£*

Travelling Expenses (if chargeable) *£*

Second Surveyor's Fee (if any) *£*

Fees applied for,

19

Received by me,

19

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUES. 15 MAY 1906

TUES. 9 OCT 1906

Character Assigned

100 A1

char dk

+ NB 5.06

Lloyd's Register
Foundation

ABN32-0078

joggled outo frame bar & taking frame rivets; double reverse bars
& base angles of boiler stools renewed. — Double reverse bars
on six floors, on each side of vessel, cut at line of bilge keelson,
& renewed to upper turn of bilge, & to upper side of bilge stringer
alternately, connected to bilge keelson by strong gusset plates.
Fore & aft brackets to boiler stools, at line of bilge keelsons, all
renewed & bilge keelsons ^{Stops where doubled, Cemented on both sides & other cement made good. R.H.} partly riveted. New Boiler shipped
barling beams of main, spar & bridge decks refitted; fore & afters
and steel main deck replaced: boiler casing (starb side) at line
of main deck, in way of side bunker, cropped & renewed in lower
part for length of boiler space, together with the coaming angle
casing in upper part, also cropped below level of bridge deck
beams, & renewed to top height, together with its adjoining tieplate
& coaming angle, casing top renewed & new lower & upper funnel,
air casing & bonnet, fiddle, gratings & ventilators, supplied & fitted.
Wood planking of spar & bridge decks, renewed to suitable shifts
caulked & painted as required.

Ridley Town.

ANCHORS.

[illegible]

CHAIN CABLES.

[illegible]