

51378

Report of Survey for Repairs, &c., of Engines & Boilers.

No. (Received at London Office, TUES 9 DECEMBER 1890)
 No. in Reg. Book. Survey held at London Date of Writing Report Dec 8th 1890 Port of London
 85 on the Machinery of the s.s. "Jasper" Date, first Survey Dec 5th Last Survey Dec 6th 1890
 Tonnage Gross 1250 Master J. Douglas No. of Visits 2
 Net 811 Vessel built at Dundee By whom W.B. Thompson When 1883 YEAR MONTH
 Registered Horse Power 99 Engines made at do: When 1883 Boilers, when made (Main) 1883 (Donkey) 1883
 No. of Main Boilers 1 Owners Dundee Steam Line Ltd Port Dundee Voyage
 Steam Pressure in Main Boilers 100 If Surveyed Afloat or in Dry Dock Afloat Class of Vessel & Machinery +100 A.I. 8.90
 in Donkey Boiler 60 (State name of Dock.) Fresh wharf. (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) Shanck Hull 4-88

Last Survey No. 540 Port Duars. Dun. No 1-88

Particulars of Examination and Repairs (if any) Annual Boiler Survey.

B.S. 9-89

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time? Yes.

If this was not done, state for what reasons? The main boiler was in use, for discharging cargo.

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler? }

Examined Donkey Boiler and safety valve, a patch in firebox extending about $\frac{3}{4}$ round has been leaking, causing the rivets at the bottom of the firebox to corrode, recommended that this patch should be re-riveted where leaky, and that the defective rivets at bottom should be renewed - Thirteen rivets have been renewed.

It is proposed to open up the main boiler for survey, and to complete the repairs to the Donkey Boiler when the vessel reaches the Zyne - see attached telegram.

The Newcastle Surveyors have been advised -

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification and notation of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1/89, B. & M.S. 1/89, or L.M.C. 1/89, as the case may be.)

as far as seen the machinery of this vessel is eligible in my opinion to remain as classed to have B.S. 12-90 recorded in the Register Book subject to the completion of Survey,

Office or Registration Fee (per Sec. 27).....	£ : :		Fees applied for
Survey Fee (per Section 28)	£ : 10 : .		by Newc. Surveyors
Special Damage Fee (per Section 28)	£ : :		
*Certificate (if required) as per margin	£ : :		received by me,
Travelling Expenses (if chargeable).....	£ : :		18

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

FRI. 17 APR 1891



© 2019

FRI. 13 FEB 1891

Lloyd's Register Foundation

LONG91-0325

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that this vessel is eligible to remain as classed, and that this Survey be noted as part of the Berlin Survey.
note. This report should be forwarded to the Surveyors at Newcastle for their guidance re to the repair of the deckhouse
Boiler & Completion of the Survey

H.A.
11-12-20