



D  
56219. Jan.

The bowsprit was slightly indented on port side; this has been faired in place. The cement wedging ~~is~~ around bowsprit were removed for examination of same, & of the fastenings, but all were found in good order. The gibson was carried away & has been renewed with the greater part of head gear. The lubstang bent, has been repaired.


The fore peak was full of water, <sup>has been</sup> ~~was~~ cleared out & iron work found in good condition & cleaned & coated.

The vessel was docked for these repairs, & her bottom, examined & is in good condition ~~has been~~.

A.P.H.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation