

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 22-1-42

When handed in at Local Office 23-1-42

Port of Falmouth

No. in Survey held at Falmouth

Date, First Survey 20-8-41 Last Survey 13-1-42

19

26881 on the Wood, Iron or Steel M/S. KONGSGAARD

(No. of Visits) 55

TONNAGE:-

GROSS 9467

UNDER D.R. 8793

NET 5677

Built at Malmo

Owners Skibs A/S S. G. Svane

Managers A. G. Svane

By whom H. C. Svane

When 1937

YEAR

MONTH

8

Owners' Address

(if not already recorded in Appendix to Register Book).

Port belonging to Stavanger

Surveyed Afloat or in Dry Dock? Both

Name of Dock N-3 Dry Dock

Destined Voyage

Cell D/Bor D/Ba

total capacity

feet; u E&B

tons. F.P.T

feet; f

tons; A.P.T

feet

tons; M.T

feet

tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 22785. Port SWS.

Social Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and Items remaining to be done the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and object of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters relating to this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined Yes, not required

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER,

Date of Initial Survey,

Date of last Survey and of Periodical Surveys.

Machinery and Boiler Surveys (including date of N.B., if any).

+100A1 2.41

+L.M.C 8.37

D.B.S 9.40

T.B. 2.41 PL

Carrying Petroleum in bulk

Society's Freeboard (if assigned) as 8
Painted on Ship and now verified 3 1/4 ins.

Was a damage report made by anyone else? If so, by whom? Underwritten Surveyor

IRS, OR EXAMINATION AS PER RULE, FOR

Damage. Special Survey N-1

Oil Engines

Damage stated to have been caused through the vessel being in collision with S.S. "TREWORLAS" on the 17 June 1941 and by enemy action on the 27 June 1941 and placed on dry dock and the following damage repairs were satisfactorily carried out:-

1. Enemy Action

2. Plating. Numbered from aft

Steel plate N-9, fairied in place

3. Port Side. Numbered from aft

Stake N-11 plate, removed, fairied and refitted

" N-7.8 plate, removed

" N-9 plate, removed, fairied and refitted

Deck Bulked

TYPE OF DAMAGE REPAIRS:-	Shell Plates.	L. Frames.	R. Frames.	Floors and Bracket Floors	L. Beams.	Irons-Bottom Plates.	Dk. Plates.	Other Items:-
Repaired	18	30 Part			9 Part	30	5	as stated
Moved and Fairied or Repaired	10	11			5		3	
Repaired in place	7	4					3	

CONDITION OF THE

Decks	good	Bulkheads	good	Engine Room Skylights	good	Copper, or T.M. (State if on Felt.)
Ceilings	"	Ceiling	"	Coal Bunkers, Openings, Covers, &c.	"	When fitted, Month
Stringings	"	Cement or Asphalt	"	Oil Bunkers	good	Year
Ring	"	Rudder	good	Scuppers	"	
in way of sidelights	good	Steering gear and its connections	good	Gage Hatchways	"	
Plates	"	Windlass	"	Hatches	"	
Have pumps been examined and found efficient?	yes	Have pumps been examined and found efficient?	yes	Planking		
Have Siuice Valves been examined and found efficient?	✓	Have Watertight Doors been examined and found efficient?	✓	Gauking		
Have Ventilators and their Coamings been examined and found efficient?	yes	Have Ventilators and their Coamings been examined and found efficient?	yes	Treenails		
in Plating	"	and found efficient?	yes	Breasthooks & Stemson		
anks been examined internally?	yes	Air and Sounding Pipes	good	Transoms, Pointers & Outches		
anks been tested?	yes	Doubling Plates under Sounding Pipes	yes	Timbers of Frame at openings		
				" at other places		
				Stringays, Clamps & Shelves		
				Sailing		
				(State if examined.)		

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1-38," or "to remain as classed and to have record of survey, 1-38, and the notations of No. 1-38."

is in efficient condition and eligible in my opinion to remain as classed and to have fresh record of survey 1-42 and notation of S.S. FALMOUTH 1-42, subject to indicated plating fittings (Patches) in way of N-2.3 being tanks and prop. shafts (Starboard Quarter) and plating etc. port side forward being dealt with at the Owners convenience. Deck plating between pump room & bridge (E.W. 3.41) to be examined and repatched. The prop. shafts to be painted with special paint and given fresh lead bushings. Present state of shell plating of frames in way of aft pump room.

Survey Fee (per Section 20) £ 25 10 0

Enemy Action £ 89 5 0

Special Damage or Repair Fee (if any) £ 15 15 0

Travelling Expenses (if chargeable) £ : :

License Fee £ : :

Second Surveyor's Fee (if any) £ : :

Fees applied for, £ 23 19 0

Received by me, £ 19 0

19

Surveyor to Lloyd's Register of Shipping.

© 2020

Committee's Minutes

Character Assigned

Dele! - DB (W.T.) - 1718

FRI. 12 FEB 1942

AD. Morris

Lloyd's Register Foundation

"C" Stake N° 10.11, removed
 "D" " N° 5.6 removed
 D " N° 7, removed, fairied and refitted
 E " N° 9, removed, fairied and refitted
 E " N° 10.11 removed
 E " N° 12 fairied in place
 F " N° 10.11.12, removed
 G " N° 11.12, removed
 G " N° 13, removed, fairied and refitted
 H " N° 11.12, removed

Shorestakes T 11, removed, fairied and refitted

" T 12.13, removed

Two shell doublings in way of pump room wing, port side removed

Bulge Keel Port Side

One length of bulk plate and one length of tie bar removed

Two lengths of bulk plate and two lengths of tie bar removed,
fairied and refitted

Bottom Longitudinals Port Side. Numbered outboard from centre girders

N° 4 Centre Tank

N° 3.5.6 copped and part removed, all new bolts welded

Pump Room. N° 1.2.3.4.5.6, removed, fairied and refitted

Thirteen end brackets removed

N° 2 Wing Tank Port Side

N° 7.8.9.10 copped and part removed, all new bolts welded

When Anchors or Cables are supplied, the particulars are to be reported in the following form :—

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.			WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.	
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
1st Bower ...																	
2nd "																	
3rd "																	
Collective Weight.																	
Stream																	
Kedge.....																	

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

Number of Certificate.	Length and size supplied.		Test per Certificate.		WEIGHT OF CHAIN CABLE.		Length and size per Rule.		Description.	Makers of Cables.	When and where tested and Superintendent.
	Length.	Diam.	Statu- tory.	Breaking.	Supplied.	Per Rule.	Length.	Diam.			
	Fathoms.	Ins.	Tons.	Tons.	Cwts. qrs. lbs.	Cwts. qrs. lbs.	Fathoms.	Ins.			
Iron Stream Chain or Steel Wire....											

Front back bars removed

N° 3 Wing Tank Port Side

N° 7.8.9.10, fairied in place at after end

Sides Longitudinals Port Side. Numbered below deck

N° 2 Wing Tank.

N° 1.2.3.4.6.7.8.9.10.11.12.13.14 copped and part removed

All new bolts welded

Pump Room Wing Port Side

N° 1.2.3.4.5.6.7.8.9.10.11.12.13.14, removed

M.S "KONGSGAARD"

Damage Repairs Continued. Enemy Action

Sides Longitudinals Port Side. N° 3 Wing Tank

N° 1-2-3 cropped and part renewed

N° 4-5 cropped, part removed, fairied and refitted

N° 6-7-8. 9-10-11 cropped and part renewed

N° 12-13-14 cropped, part removed, fairied and refitted

Longitudinal Bulkhead Port Side

Lower strake cropped via inches forward of transverse N° 57 and renewed to existing butt between transverse 52/53 with intermediate butt as originally 55/56 (2 Plates)

All new bulkhead plating riveted

2nd Strake from Bottom

Cropped and part renewed from between transverse 52/53 to butt between transverse 56/57 with intermediate butt as originally between transverse 53/54 (2 Plates)

3rd Strake from Bottom

Removed from butt between transverse 51/52 to butt between transverse 57/58 with intermediate butt as originally between transverse 54/55 (3 Plates)

4th Strake from Bottom

Cropped and part renewed from between transverse 52/53 to butt between transverse 56/57 with intermediate butt as originally between transverse 53/54 (2 Plates)

Top Strake. Cropped and part renewed from butt between transverse 52/53 to immediately forward of transverse N° 56 and with intermediate butt as originally between transverse 56/57 (2 Plates)

Stiffeners Horizontal. Numbered below deck. In way of N° 4 Links Tank N° 1-2-3-4-5-6-7-8-9-10-11-12-13 renewed. All stiffeners welded to 'thwartship' bulkheads. Fifteen brackets to 'thwartship' bulkhead renewed

In Way of Pump Room

N° 1-2-3-4-5-6-7-8-9-10-11-12-13 renewed. All stiffeners welded to 'thwartship' bulkheads. Shelf plates and lugs N° 1-13 inclusive on port side of bulkhead in pump room being renewed

Stiffener brackets & lugs to 'thwartship' bulkheads N° 1-13 inclusive renewed.

In Way of N° 5 Links Tank

N° 5-6-7-8-9-10-11-12-13, cropped, part removed, fairied and refitted

New butts welded.

Stiffener brackets to 'thwartship' bulkheads N° 6-13, renewed, fairied & refitted

Transverse Longitudinal Bulkhead (Welded to Bulkhead)

N° 53-54 renewed complete

Transverses on Bottom (Welded to Shell)

N° 53 Plating cropped at N° 3 bottom longitudinal, outboard portion renewed, fairied and refitted; new buttstrap made & fitted

20
5800 - 4111

© 2020

Lloyd's Register
Foundation

M.S. "KONGSGAARD"

Damages Repairs continued

Additional connection bar made and fitted to short girder on N-3 bottom longitudinal taking transverse N-52

Face has crooked and part unrued and new butt unloled

Stiffeners taking bottom longitudinal and longitudinal bulkhead
stiffeners N° 12 + 13, removed, fair'd and refitted

N°54 Plating cropped at N°3 bottom longitudinal, outboard portion
reversed and new buttshp made - fitted

Additional connection bar fitted to short girder on N°3 bottom longitudinal taking transverse bulkhead N°55

Face bars upright - front rounded - nose blunt undulated

Stiffeners taking bottom longitudinal and longitudinal stiffeners
N° 12-13 mm wide. Inboard portion of transom fitted in place

Boundary Bars. Double bars to click and bottom shell warped and
part rounded - butt welded

Longitudinal Bulkhead. Starboard Side. In way of Pump Room
Welded patches made - fitted in way of holes in 2nd stabs from bottom
below N° 9 stiffener from deck and top forward corner. Welded in top
stabs and stabs below, fared in place. N° 3-5 stiffeners fared in place.
Forward brackets - lug on N° 1 stiffener removed, after bracket on N° 2
stiffener removed, fared and refitted.

N-53 Web. Face bar crooked - front removed, painted & refitted and new batt
added. Web plates painted in place

18-54 Web. Web plate + fan bar fastened in place

Transverse Bulkhead N° 52 (N° 3-4 Center Tanks)

Part web face has collapsed at N°3 stiffener, part removed, fairing re-fitted
and new butt welded

Combs web face has crooked at N 4 stiffens, part removed, fair'd & refitted
and new bath melted. Port-combs web plates fair'd in place

Transverse Bulkhead N-55 (1/4 Lents tank - Pump Room) (1/4)

All removed plating riveted at seams & butts, but welded for spell deck
and first longitudinal bulkhead. All stakes of plating capped, and first side
removed with suitable shift of butts

Stiffmuss. Numbered below check

N² 1-13 inclusive cropped to starboard side of center line and port portions removed with new butts welded

Port side Web + brackets to bottom shell and deck longitudinal
in line with same as opposite side of bulkhead, Web and brackets
welded to bulkhead plating. Removed complete together with shot girder
to transverse N° 54

Links thin web. (Welded to Bulkhead). Platting capped and lower portion runned with new butt riveted. Fair has now been complete

Stiffened unruled, fairing and reftited. Two brackets to stern girder unruled
Starboard side, two brackets to bottom shell - deck longitudinals in line
with same on starboard side of bulkhead. Fairing in place

M.S. "KONGSGAARD"Damage Repairs continued

Bottom longitudinal connection bars. Welded to top flange of longitudinal and bulkhead. N° 1-2-4-5-6 port & N° 1-2 starboard removed
Transverse Bulkhead N° 56. (N° 5 Laminar Tank - Pump Room)

All removed plating riveted at seams - butts, but welded to bottom shell, deck and port longitudinal bulkhead

Bottom. 2nd + 3rd strakes copped at either side of bulkhead line to obtain suitable shaft of butts and port side portions removed

4" and top strakes and on starboard side between starboard web and starboard longitudinal bulkhead, fairied in place

Stiffeners. Numbered below deck

N° 6 to 11 inclusive, copped clear of new plate butts, port portions, removed fairied and refitted and new butts welded

Port side web - short girder to transverse N° 57. Face bar & web removed, fairied and refitted

Web plate - short girder plate, fairied in place

Bottom longitudinal connection bars. Welded to top flange of longitudinal - bulkhead. N° 5+6 removed. N° 1-2-4, removed, fairied & refitted

N° 2 Side Tank Port Side. N° 51 Transverse. (Welded to shell)

Side transverse plate copped at N° 5 longitudinal below deck and lower portion removed with new quadruple riveted overlap. Side transverse face bar copped between N° 4-5 longitudinals and lower portion removed, fairied & refitted with new butt welded

Stiffeners removed, fairied and refitted

Bottom girder plate face bar copped - port removed, fairied and refitted and new butt welded. Bottom girder plate, fairied in place

N° 53 + 54 Transverses (Welded to shell - longitudinal bulkhead)

Removed complete at side - bottom (8 Plates) - (34 Angles)

N° 52 + 55 Wash Bulkheads. Welded to shell, deck & longitudinal bulkhead

Removed complete (12 Plates) (94 Angles)

Forward Bulkhead of N° 2 Wing Tank Port Side N° 56 A. (Welded to shell, deck and longitudinal bulkhead)

Removed complete, 5 plates, 16 flanged plates, 13 Bull Angles, 21 angles.

Pump Room Port Side. Transverse Bulkhead N° 56 in way of N° 2 Wing Tank Port (Welded to shell, deck, & longitudinal bulkhead)

All plating, stiffeners and bottom longitudinal bars removed complete 5 plates, 13 Bull Angles, 14 angles.

Stiffener brackets & lugs removed, fairied and refitted; 26 flanged brackets, 11 angle lugs, 2 bracket lugs

N° 3 Wing Tank. Port Side. N° 57 Transverses. (Welded to shell and longitudinal bulkhead) Side transverse plate copped between N° 5+6 longitudinals

below deck and lower portions removed with new quadruple riveted overlap. Face bar on side transverse, removed, fairied & refitted

7/00
6
5
4
3
2
1
0
-
1/15



Lloyd's Register
Foundation

M.S. "KONGSGAARD"Damage Repairs continuedN°3 Wing Tank Port Side continued

Transverse floor removed. Face bar on transverse floor removed, fairied and refitted. Stiffeners on sides & bottom transverses, removed, fairied & refitted (7)

Upper Deck Port Side. Numbered from after end of Bridge. A Stake in centre.

A 3, fairied in place. B 3, removed. B 4, fairied in place

C 3, removed, fairied and refitted. C 4, removed and extended; in 2 plates

C 5, cropped and fairied in place. D 3, removed, fairied & refitted

D 4, removed, fairied and refitted

Stringer E 3-4 removed.

Doubling plate in way of Samson Post and cargo pipe removed

Deck stringer bar removed, fairied and refitted

Deck Centre Girder in way of Pump Room (welded to transverse bulkheads)

Removed complete with the exception of two brackets. 3 Plates, 2 Bulk Angles

Two brackets removed, fairied and refitted

Deck Centre girder in way of N°4 centre tank

Plate cropped and fairied removed; 2 Brackets removed

Deck Longitudinals (welded to transverse bulkheads at ends) Numbered from centre line.

In Way of Cargo Tanks

N°1 Cropped & fairied removed, fairied and refitted, new butt welded

N°2, 3, 4, 5, 6, 7, 8, 9, 10 Cropped, fairied removed and new butt welded

In Way of Pump Room

Four longitudinals in centre and one starboard wing removed

Four longitudinals in port wing removed, fairied and refitted

One longitudinal bracket removed

Deck Transverse N°53-54 in way of N°2 Wing Tank removed complete (welded to shell, deck and longitudinal bulkhead). 2 Plates, 2 flanged plates & 10 angles

Deck Transverse N°53 in N°4 centre tank; plate cropped and fairied removed with new butt welded. Face bar cropped and fairied removed, fairied & refitted; with new butt welded.

Deck Transverse N°54 in N°4 centre tank, plate cropped to port side of centre line and port portion removed with new quadruple riveted overlap. Face bar cropped and fairied removed and new butt welded. Fair stiffeners removed.

Short deck girder in way of port web on N°55 bulkhead in N°4 centre tank removed

Deck transverse N°57 in N°3 wing tank, plating fairied in place

Face bar cropped and fairied removed, fairied and refitted with new butt welded

Cargo Tank Hatches. N°2 Port hatch, removed complete

N°3 Port hatch, removed, fairied & refitted

W1197 5/5 0089 00

Port of Falmouth

Continuation of Report No. 10106 dated 23-1-42

on the

M.S. "KONGSGAARD"Damage Repair continued

Foreside deck on port side, new flush deck plate fitted and welded in way of splinter hole. Upper deck plating in forecastle stow, fairied in place

Tank Testing

N^o 1-2-3-4-5-6-7-8-9-10 centre cargo tanks; N^o 1-2-3-4-5 wing cargo tanks, port and starboard, fore and after cofferdams, fore deck tank, fore and after peak tanks, nose bunker, engine room double bottom tanks, fresh water tank in cruiser stem space tested by heat of water on completion of repairs and found tight. Pump room flooded and shell cargo, bunkering, steam and gas lines examined

All valves, pipes and fittings in way of damage removed, renewed or replaced as necessary and afterwards tested

All new and disturbed work cleaned and coated

All removals as found necessary.

2 Collision DamagePort Side Forward. Forecastle Shear Plates

Riveting plate cuffed about bulkheads just forward of bulkhead and after part removed.

Forecastle side, aft plate forming port bulwark plate, cuffed about thirty-one inches forward of bulkhead and after part removed

Main Shear Plates

N^o 4 plate from forward, fairied in place and fastened electrically welded deck stringer plate, fairied in place.

Deck gun mount bar, " " "

Bulwark plate stay removed, fairied and refitted

Bulwark B.A. stanchion removed, fairied and refitted

Bulwark B.A. rail removed

Brackets and bungs to forecastle bulkhead removed, fairied and refitted

Rails in vicinity bended and removed as necessary

Rails and stanchions on forecastle deck and fore deck, fairied in place

Port Side After Peak

N^o 10 plate from aft in main shear plate, fairied in place

Port side hoop port and side

Bulwark plate forming port hoisting plate and port side plate removed

N^o 2-3 plate from forward on port side, removed, fairied and refitted

N^o 7-8 plates from aft on main shear plate, removed, fairied and refitted

N^o 6 plate " " " " fairied in place

N^o 6-7 plates from aft on 1st whale below main shear plate, fairied in place

N^o 3 stanchion on hoop to boat deck, removed, fairied and refitted

Hoisting pipe and dubbing plate, removed and refitted

Bulwark B.A. angle rail, removed, fairied and refitted

Two B.A. stanchions and bungs, removed, fairied and refitted

Bulwark plate stanchion removed

W197 - 0089 - 1011

© 2020

Lloyd's Register
Foundation

M.S. "KONGSGAARD"

Damage Aspects continued Collision Damage

Port side prop. post and ribs continued

Deck stringer plate, fairied in place

Deck girders bar fairied in place

Bracket and lag to prop. post removed

Prop. post wing plate, new piece welded in and connection angles fairied in place

Shell bar on prop. post removed

Portlights and frames removed as necessary, rehandled and refitted (12)

Frames in way of prop. side and main deck cuffed and removed
fairied and refitted (4)

Wood sheathing on ship's side, portlight frame bars, bulkheads, etc.
in lower accommodation removed and refitted with fast new material
as necessary.

Two brackets and lags from upper deck bulkhead to shell, removed, fairied
and refitted.

Fuel oil tank in upper flat listed and mitre removed as necessary

Internal work in way of prop.

N° 8 & 4 webs from prop. post, removed

N° 1-2 " " " , removed, fairied and refitted

N° 5 web " " " , fairied in place

Twelve web shell bars, removed, fairied and refitted

Eight web deck lags " " " "

One prop. post stiffener " " " "

All removed as found necessary. all new & disturbed work cleaned & coated

Collision Damage. Deferred Repair

Port Side Forward

" Strike N° 18 plate (N° 8 from forward) to be removed, fairied and refitted

" " N° 18 " (N° 5 " ") to be removed, fairied and refitted

" " N° 19 " (N° 4 " ") to be fairied in place

N° 2-3-4-5-6 ribs longitudinal to be dealt with

Flanged bracket to upper deck bulkhead on N° 2 longitudinal to be dealt with

Forward web plates between N° 5-6 longitudinal " " " "

Bracket from deck beam to upper deck bulkhead " " " "

Forward Crossover Port Side

N° 2-3-4 wash plates below deck to be dealt with

N° 2-3-4 " shell bars " " " "

N° 5 Port wing tank and forward crossover twisted and found tight

Shell has twisted in way of prop. hold. The foregoing are considered to be
unsatisfactory and recommended to be dealt with at the owners convenience


Special Survey N° 1

Kessel placed in dry dock. The bottom, rudder and stern frame channel
examined and coated, now satisfactory

Deferred
repairs

7/8
W1197 - 0089

© 2020



Lloyd's Register
Foundation

Port of Falmouth

Continuation of Report No 10106 dated 23-1-42 on the

M.S. "KONGSGAARD"Special Survey N°1 continued

All centre cargo tanks, all wing cargo tanks, cisterns, oil fuel and bunker, fore deck tank, fore and after peak tanks, pump rooms, all double bottom tanks, fresh water tanks examined internally, afterwards tested as required by the Rules and found tight.

Panels, fore hold, machinery spaces, steelwork exposed throughout including under sidelights, examined and put in satisfactory condition

Decks, general equipment, hatchways, hatches, covers, casings, masts, rigging, ventilators, coamings, windlass, steering gear and its connection, funnels, air and venting pipes examined and put in satisfactory condition
Steaming plates fitted upon venting pipe

Freeboard measured

Wear & Tear Repairs

Main repairs carried out

Rudder lifted, main prop removed on account of welding repair in way of front coupling, coupling face of new main prop machined in shop, afterwards fitted to rudder, tried under working condition and found in order.

New main prop stamped L.R. 6974 H.M.C. 14.3.41

S.H.L Indented shell plating etc and deck plate (E.M. 2.41) examined and found satisfactory

The indented when + adjacent stake of shell plating and framing in way abaft pump room on port side have been dealt with at this time.

NOTE The name of the vessel given in Belfast report N° 13016 as "TRAMORLAW" should be "TREWORLAS"

8/8
0089 - 14511

A.D. Morris

© 2020



Lloyd's Register
Foundation