

REC'D NEW YORK MAY 18 1923

(Received at London Office)

No. 4581

RETAILED

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 16 May 1923 When handed in at Local Office 16 May 1923 Port of Philadelphia.

No. in Survey held at Philadelphia 37914 Date, First Survey 1st Novth 1922 Last Survey 7 May 1923
Reg. Book. (No. of Visits 34) 1923.

52448. on the Wood, Iron or Steel Sys ALAMEDA.

Master

TONNAGE:-
GROSS 7222
UNDER D.K. 6382
NET 5362.Built at Philadelphia By whom W.Cramp Sons & Co. When 1919.
Owners Arnold Craig W.Cramp Sons SMC Sys Port belonging to Philadelphia.
Owners' Address Richmond Morris Sts. Philadelphia.

Surveyed Afloat or in Dry Dock? Yes Name of Dock Sun ABCo. Destined Voyage San Pedro, Cal.

WB=Cell DB or DBa feet; uE&B feet; f feet; t tons. FPT tons; APT tons; MT feet tons.

N.B.-All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
X for Special Survey.
Date of last Survey and of Periodical Surveys.YEAR.
MONTH.
Years assigned now expired.

Machinery and Boiler Surveys (including date of N.B., if any).

100 A.1.

(Condensed)

Last Report, No. Port Society's Freeboard (if assigned) as painted on Ship and now verified 8 ft. 0 ins.

Year of Survey.

Surveying stamp - held on the Machinery of the Ship
If so, is the Report sent now, or when will it be sent?

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? ✓

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Classification, Alterations and Damage.

Now done. - Classification - Vessel placed on Pontoon. Bottom and Decks examined, cleaned and re-coated. Anchors examined. Chain cables ranged and examined (for particulars see First Entry Report herewith). Hawers and warps examined. Boats examined. All main and summer Cargs oil tanks, cofferdams, fuel oil tanks, Reserve feed water tanks, double bottom tanks and forward and after peak tanks examined internally and tested under pressures required by the Rules and found efficient. Holes. Twin decks. Bunkers, and machinery spaces examined, cleaned and recoated. Shell plating including plating under sidelights examined. It was not considered necessary to drill the shell plating at this time. A number of rivets

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed	1	Transverse	-	-	4 Transverse	1	10	Engines & Boiler Cases all renewed.
Removed and Fairied or Repaired	34	4	-	-	each end	16	64	Bunkie Hatch removed & replaced.
Fairied or Repaired in place	-	-	-	-	-	-	-	-

PRESENT CONDITION OF THE	Stringers	Good	Dblng. Plates under Sounding Pipes	Good	Copper, or Y.M. of Wood Vessels (State if on Feet.)
Decks	Inner Bottom Plating	4	Engine Room Skylights	4	When put on Month
Caulking of Decks	State if Tanks have been examined inside	Yes	Coal Bunkers, Open'gs, Lids, &c.	5	Boats
Waterways	State if Tanks now tested	Yes	Scuppers	5	Masts, Yards, &c.
Coamings	Bulkheads	Good	Cargo Hatchways	5	Condition, how ascertained
Beams & Fastenings	Ceiling	Good	Hatches	5	(State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Good	Planking of Wood Vessels	5	Sails
Caulking of ditto	Rudder	4	Caulking	ditto	Equipment letter
Rivets	Steering gear and its connections	4	Treenails	ditto	3 BISIK.
Breasthooks & Crutches	Windlass	4	Breasthooks & Stemson	ditto	Anchors, No. of
Transoms	Have Pumps now been examined and found efficient?	Yes	Transoms, Pointers, & Crutches	ditto	Cables (State if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	None	Timbers of Frame at openings	ditto	300 fm. size 2 1/2
Reverse Frames	Have Watertight Doors now been examined and found efficient?	None	Ditto ditto at other places	ditto	300 fm. size 2 1/2
Floors			Stringers, Clamps & Shelves	ditto	Rule length
Keelsons			Salting	ditto	Hawser & Warps

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss. No. 1-15 and ptND15, &c."

This vessel is now in a good and efficient condition, eligible in my opinion, to be classed 100 A.1. Carrying petroleum in bulk with longitudinal framing, and record ss. No. 1-23.

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) per Sec. 29 \$120.00

Travelling Expenses (if chargeable) Entered at First Entry Dept.

Second Surveyor's Fee (if any) £

New York MAY 2 1923

Fees applied for

16 May 1923

Lloyd's Register

Report

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

See attached Report form 1A



© 2020

Lloyd's Register Foundation

W346-0062 2/3

RETAIN**J. S. "ALAMEDA"**

rivets removed from various parts of the vessel, and quality of rivets and character of countersinking and workmanship found satisfactory. Cementing examined and found good and adhering to the steel plating. Decks examined. Mast examined (no mast wedging). Rigging examined (see Report herewith). Windlass renewed. The new cable supplied is 2 $\frac{1}{2}$ " diameter (in excess of rule diameter), and the new windlass is suitable for 2 $\frac{1}{2}$ " diam. Cable. Chain locker cleared and examined and re-coated. Windlass & Capstans seen working satisfactorily. Steering gear examined, overhauled, put in good working order and seen working satisfactorily. Hand pump seen working satisfactorily. Scuppers examined. Hatches examined and found in good condition. Dubboards reported, assigned, and marks verified.

(2) Alterations.- Magazines and shell rooms in After end of machinery space and in Fore Hold, together with ammunition trunks, also radio house forward of Poop deck, above th. level of Poop deck all removed and riveting in way of attachment to same made good.

(3) Damage.- Stated caused by fire off Cape Henlopen in May 1922 when in the service of the U.S. Navy, and by striking wharves etc. at times not stated.

Damage in way of Machinery Spaces and above same. The following plates removed, annealed as necessary, fared & replaced, viz:

Shell Rating.- Poop side.- Port side upper stroke. Plates nos 7. 8. 9 + 10.

" " lower stroke " 15. 16. 17. 18 + 19.

" " Starbd " upper " " 7. 8. 9 + 10.

" " " lower " " 15. 16. 17. 18 + 19.

" Sheerstrake (M) Port " Plates. 14. 15 + 16

" " Starbd " " 14. 15 + 16.

" L Stroke. Port " " 14. 15 + 16.

" " Starbd " " 14. 15 + 16.

" K " Port " " 13. 14. 15 + 16.

" " Starbd " " 13 + 14.

" J " Port " " 14. 15. 16. 17. + 18.

" " Starbd " " 14 + 15.

" K " plate in L Stroke port side renewed.

Dock Plating.- Poopdeck- Six plates renewed. Thirty two plates removed, annealed, fared and replaced.

Upperdeck. - The following plates were removed, annealed, fared and replaced, viz- four storage plates each side.

Centre Strake (A). nos 5. 6. 7 + 8. B Strake. nos 45 + 6 each side.

C Strake. N° 4. 5. 6. 7 each side. D Strake nos 11. 12. 13. 14 + 15 each side.

E Strake. N° 11. 12. 13 + 14 each side.

Second deck. - The following plate were renewed, viz- Centre (A) Strake N° 13. B Strake.

© 2020

pt. 9a.

Port of Philadelphia

Continuation of Report No. 4581 dated 16th May 1923. on the

S. S. "ALAMEDA".

Deck plating (cont'd). 2nd deck. B strake. No 5 plate each side. C strake Nos. 5 & 6 each side.
D strake. No 12 each side & No 13 port side. Stringer N° 18 port side.
The following plates were removed, annealed, fairis
replaced. viz:- Four plates over boilers forward of Boiler Casing.
Three plates between Engine & Boiler Casing and twenty
nine (29) other deck plates in this deck, including four
stronger plates each side.
Boiler Casings all renewed with stiffeners as original.
Bulkhead No. 207 which formed forward bulkhead of magazine & shower room
removed, and transverse frame fitted in lieu. Transverses Nos 40, 41, & 43
renewed. Coal Bunker hatches removed and replaced.

O'Farrell

