

Wear & tear repairs.

Stem tube not reinforced with electric welding

New cone fitted to boiler blow-off air cock

H.P. piston rod cross-head nut, joint ring & rings renewed.

M.P. valve spindle and guide brasses renewed

Port dynamo cylinder and chest bored, new piston, rings & valve fitted

Ballast pump fitted with new buckets & rods.

Main stop valve spindle on p & s boiler renewed.

Steam gauge cocks renewed on all boiler tops.

Other minor repairs effected.

N.B.—If this Report is copied by copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2019

Lloyd's Register

WSIS-0192 2/2
Foundation