

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report *7th October 1935* When handed in at Local Office *8th October 1935* Port of *FREMANTLE. W.A.*  
 No. in *Survey held at Port Hedland* Date, First Survey *25th Sept* Last Survey *4th October 1935*  
 g. Book. *on the Wood, Iron or Steel Steamer "MINDEROO"* No. of Visits *Continuous*

TONNAGE— Built at *Glasgow* By whom *C. Bonnell & Co Ltd* When *1909* MONTH *4 Mo*  
 GROSS *2720* Owners *Glasgow* Owners' Address *(if not already recorded in Appendix to Register Book).*  
 UNDER DECK *1636* Managers *Bethell Gwynne & Co* Port belonging to *London*

Surveyed Afloat or in Dry Dock? *Afloat* Name of Dock *Alongside Jetty at Port Hedland* Destined Voyage *Coastal & Malay States*  
 "B=Cell DBor DBa feet; uE&B feet; f feet feet  
 tal capacity tons; FPT tons; APT tons; MT feet tons.

N.B. All alterations in the existing records should be underlined.  
 If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Report, No. *5705* Port *Sing*

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. X for Special Survey, Date of last survey and of Periodical Surveys.	Years Assigned expired.	Machinery and Boiler surveys (including date of N.B., if any).
<i>1-100 A1</i>		<i>1-LMC 3-34</i>
<i>Shade Deck</i>		<i>BS 1-35</i>
<i>8-35</i>		
<i>SS Sing. 2nd No. 3-34</i>		<i>CL 1-35</i>

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

When held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; being detailed in the body of the report, should be summarised in the form shown below. Whenever the of Anchors or Chains is reported the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case. *11-10-35 WGD/BA*

Where the Surveyor has not made a special damage report he is required to state whether he services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AS PER RULE, FOR *the purpose of ascertaining the nature and extent of which is alleged to have occurred when the vessel rested on a sand bank at Port Hedland on 14th September 1935 during a voyage from Fremantle to one via Ports. For further particulars see Log Books.*

Examinations with the vessel afloat alongside Port Hedland Jetty found.

Structure  
 Port and Starboard S.B. Tanks Division plate between Nos 4 & 5 Tanks buckled slightly, except in Port and Starboard wing spaces where the plate is fluted sharply—lastly on Port side at junction of margin angle, margin plate and ship's skin, where division plate is torn away, making No 4 & 5 Port tanks common. Top angles are slightly. (See over)

MAJOR REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Painted or Repaired								
Repaired in place								

State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or I.M. of Wood Vessels
State if Tanks now tested	Dbing. Plates under Sounding Pipes	(State if on Port).
Bulkheads	Engine Room Skylights	When put on, Month Year
Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Boats
Cement or Asphalt (State which.)	Oil Bunkers	Masts, Yards, &c.
Rudder	Scuppers	Condition, how ascertained.
Steering gear and its connections	Cargo Hatchways	(State if wedges removed)
Windlass	Hatches	Sails
Have pumps now been examined and found efficient?	Planking of Wood Vessels	Equipment letter
Have Sluice Valves now been examined and found efficient?	Caulking ditto	Anchors, No. of
Have Watertight Doors now been examined and found efficient?	Treenails ditto	Chain Locker
Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Cables (State if now ranged)
	Transoms Pointers, & Crutches ditto	length mean diamr.
	Timbers of Frame at openings ditto	(on board)
	Ditto Ditto at other places ditto	Rule length size
	Stringers, Clamps & Shells ditto	Hawser & Warps
	Sanding (State if examined.)	Standing and Running Rigging

Observations, Opinion as to Class, Recommendation, &c.:—  
 Early whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1, 2, 4, and the notations of ss. No. 1-24 and ptND24, &c."  
*in the case of this vessel, that she be classed as fit to be towed to Port of and further that she be continued as classed, subject to permanent repairs being only carried out at the earliest opportunity, the vessel being fit to carry dry stowable cargo*

Repair Fee (if any) £ 35 : - : -  
 (if chargeable) £ 11 : 10 : -  
 Surveyor's Fee (if any) £ : : -  
 Fees applied for, *8th Oct 1935*  
 Received by me, *Wm. G. Davies*  
 Surveyor to Lloyd's Register of Shipping.

Committee's Minute  
 TUE. 12 NOV 1935  
 TUE. 15 DEC 1935  
 Peter Assigned *Defered*  
*Write Sing permanent repairs*  
 Lloyd's Register Foundation







Port of FREMANTLE. W.A. Continuation of Report No. 804 dated 4th October 1935 on the  
Steel Screw Steamer "MINDEROO"

between old holes which had been plugged at some time previously.  
This appears to be the point at which the maximum stress was dealt  
N°3 Hold Port side

Lower Stringer gusset on Engine Room bulkhead slightly buckled.  
When the vessel is at a draught 16 ft aft and 12½ ft forward, there is a  
vertical bulge in the ship's side plates, extending upwards from the  
to the bottom of the second strake below the sheer strake, approximately  
twelve feet forward of after break of bridge deck and corresponding  
one frame space aft of Engine Room bulkhead in N°3 Hold. At  
draught the bottom of third strake below sheer strake is on water level.  
Tank Brackets good.

Tank bracket forming watertight division between N°3 bulge and  
Room bulge found to be good.

Queen deck floor set down slightly in first bay aft of Engine Room bulkhead  
Engine Room bulkhead buckled - a minimum six feet from Starboard side  
very badly at corner of thrust recess.

Three gussets buckled badly on tank top.  
Engine Room bulkhead buckled slightly at top corner near thrust  
Starboard screen bulkhead of thrust recess buckled at bottom for eight  
feet in Starboard side immediately above bulge in first bay in N°3 hold  
(that this hole is on the vertical bulge in ship's side)

Keelsons generally The existing joint is twelve feet aft of the division plate  
N°4 + 5 Tanks and another joint twenty four feet forward in N°4 Tank  
first bay aft of division between N°3 + 4 tanks.

### General

Unsheathed decks in side bunker spaces have been examined and appear  
to have been strained. Hull plates do not appear to have been  
strained on upper strakes. Generally the damage is confined to the  
bottoms in way of N°4 + 5 Tanks between frame N°58 and frame  
reading from aft to forward, both inclusive, i.e. 16 frame spaces.  
feet each = 32 feet or approximately ten per cent of the vessel's length.

### Recommended

The following temporary repairs are recommended in order to place  
in a seaworthy condition so that she would be fit to be towed  
Port of Repair.

### Hull

Cement box Port & Starboard Wing bays in N°4 + 5 double bottom  
each side of the division plate between these tanks.

Cement box inside tank in way of tank brackets where these have  
been torn away from margin plate in N°4 Port and Starboard double bottom.

Cement box inside N°4 Port and Starboard double bottom tanks in way of  
angles where leaks were seen during testing of tank.

Cement box inside N°5 Starboard double bottom tank in way of margin  
in first bay aft of the division between N°4 + 5 tanks where this  
angle was seen to leak during testing of tank. Also cement box in  
adjacent to the above cement box.

Cement box each side of the keelson in the first bay of N°5 double bottom  
tank aft of the division between N°4 + 5 double bottom tanks to prevent  
N°5 Port & Starboard tanks from becoming common.

Cement box in first frame space aft of the Engine Room bulkhead in N°3  
Lower hold where the hull plating is bulged vertically on the Port and  
Starboard sides. The cement boxes to extend the full depth of the  
Lower hold, down to the bulges.

The whole of the above temporary repairs have now been seen satisfactorily  
completed, and N°4 + 5 double bottom tanks, Port and Starboard, tested and  
found tight, also all bulges have now been seen quite dry and the vessel  
seems to be watertight as regards Hull and Tanks and an Interim  
Certificate has been issued to the effect that the vessel is fit to be  
towed to Port of Repair and that she be continued as classed, subject  
to permanent repairs to Engines and Hull being carried out at the earliest  
opportunity.

The items relating to Hull and Tanks in the foregoing report are  
clearly due to damage.

Attached to this Report also is an outline of the particulars and the  
sequence of work to be done to Engines and Hull in order to place the  
vessel in the same condition as she was in prior to grounding at Port  
Bedland, together with an approximate estimate of the cost of such  
permanent repairs, which information was requested by the Ship's Agents  
and Lloyd's Agents.

W. J. Davies



© 2020

Lloyd's Register  
Foundation

MS37-0267