

The middle class is contemplated
Damage due to stranding
Machinery opened out & examined
New propeller blades fitted.

N.B. - If this Report is copied by Clipping Press, special care must be taken that the copying paper is not so much damaged as to spread the ink, or to cause it to show through to the other side.

Rpt. 9a.

Port of Great Harboursport Continuation of Report No. 14597 dated 24th Feb 13 on the

S.S. "Bocton"

Four new bronze propeller blades fitted. The shaft-
ing tested for alignment and found fair.

The air circulating feed and bilge pumps
and their respective valves good. Pump gear
good. The condenser unhauled tested and found
good. The holding down bolts examined and
tested. The sea connections removed from the
port side to engine room to admit of removal
of shell plate all unhauled and efficiently
refitted in place. The bilge and ballast directing
valve and the bilge injection unhauled good.

The Auxiliary feed pump. Small control
feed pump and the three donkey engines un-
hauled and made good. New piston rod fitted
to Hot control pump.

The air bearings connected with the forced
draught installation and the boiler casings
were started unhauled and made good.
The main and superheater damper gear un-
hauled and made good. The boilers cleaned
out internally and the fastenings examined.
Pump cushions were disturbed made good.
The steering engine examined. The winch con-
-denser unhauled & tested good. The electric
light installation was disturbed made good.

Success Issues.



© 2021

Lloyd's Register

Foundation

WS47-00532/2