

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report. 20th July 1915 When handed in at Local Office 22 July 1915 Port of CARDIFF.

No. in Reg. Book. Survey held at Cardiff Date, First Survey 5 July 1915 Last Survey 17 July 1915
on the Wood, Iron or Steel S/S Monitoria (No. of Visits) 9
Master

1443 TONNAGE: Built at Sunderland By whom Osborne Graham & Co. When 1909
GROSS 1984 Owners' Address Priesson Shipping Co Ltd
UNDER D.W. 1749
D.W. 1165
Surveyed Afloat or in Dry Dock? Dry Name of Dock Wm. Hudson Slipway
WB=Cell DB or DBa feet; uE&B feet; f feet; total capacity tons. FPT tons; APT tons; MT tons.

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Report, No. 36916 Port Off

CHARACTER.
For Special Survey.
Date of last Survey and of
Periodical Surveys.

Particulars of Classification (which must be inserted
precisely as in Register Book & Supplements).
Machinery and Boiler
Surveys
(including date of N.R., if any).

SS 100A1
SS Apel. No 1. 4
Apel. 8/14
NNTB 07
Repilled 09

Society's Freeboard (if assigned) as per
Painted on Ship and now verified.

image cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Yes. not required

Was a damage report made by anyone else? If so, by whom? Admiralty Surveyor

AIRS, OR EXAMINATION AS PER RULE, FOR Docking and damage.

Vessel placed on Slipway. bottom and rudder cleaned and examined.
Rudder lifted and lined up. Bottom recoated.

The following repairs carried out for damage stated caused by colliding
with the Admiralty vessels "Lancashire Bat" and "Russel" at Scapa Flow.
on 27th Sept 1914 and 1/3rd January 1915.

done. Starboard side No. 2 plate on forecastle sheer strake starboard side
removed faired and put back. No 3 plate faired in place. 2 frames faired in place.
The Nos. 2 and 7 plates (corrugated) have been removed faired and put back.
No. 3 plate faired in place. 2 frames faired in place. 1 gusset plate removed
at stroke below sheer. The 5 plates faired in place. Noted a number of insertions in
the plates in Port Star. corrugated strakes. paint & Caulking sound. Vessel's efficiency not affected.

MARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed	3							
Removed and Faired or Repaired	3	4						
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers only part seen	Dihing. Plates under Sounding Pipes not seen	Copper, or I.M. of Wood Vessels
Good		good	(State if on Felt.)
Decking of Decks	"	Engine Room Skylights.	When put on, Month
Stairways	"	Coal Bunkers, Open'gs, Lids, &c.	Year
Comings	"	Scuppers	Boats
Fastenings	only part seen	Cargo Hatchways	Good
Outside Plating	Good	Hatches	Masts, Tails, &c.
Welding of ditto.	"	Planking of Wood Vessels	"
Welds	"	Gaulking ditto	Condition, how ascertained
Bathrooks & Crutches	not examined	Treenails ditto	(State if wedges removed)
Ansons	"	Breasthooks & Stemson ditto	no
James	only part seen	Transoms, Pointers, & Crutches ditto	Sails
Inverse Frames		Timbers of Frame at openings ditto	Equipment letter
Girders	not examined	Ditto ditto at other places ditto	Anchors, No. of 380/15 IK
Seilsons	"	Stringers, Clamps & Shelves ditto	Cables (State if new ranged) no

General Observations, Opinion as to Class, Recommendation, &c.:— This vessel so far

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1/11," or "to remain as classed and to have record of survey, 1/11, and the notations of No. 1-11 and pNDL, &c."

This vessel is in efficient condition and in my opinion eligible to be retained as at present classed in the Register Book with fresh record of survey 7. 15.

Survey Fee (per Section 28) £ 3 : 3 : 0
Special Damage or Repair Fee (if any) £ 0/0/0
Travelling Expenses (if chargeable) £ 0/0/0
Second Surveyor's Fee (if any) £ 0/0/0

Fees applied for,
22 July 1915
Received by me,
23/7/1915
24/7/1915

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute ✓ TUE JUL 27 1915

Character Assigned 100A1 W.

Cargo battens not fitted

J.O.C.B. 10/10/15

RS/15



© 2020
Lloyd's Register
Foundation