

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

TUE 3-OCT. 1916

Date of writing Report 30 Sept 1916 When handed in at Local Office 30 Sept 16 Port of NEWCASTLE ON TYNE.No. in Reg. Book. 263 Survey held at North ShieldsDate, First Survey 20 Sept 16 Last Survey 29 Sept 1916on the Machinery of the Wood, Iron or Steel of firmTonnage { Gross 3806  
Net 2473Vessel built at Sunderland By whom J. L. Thompson & Co.

Master

YEAR. MONTH.

Registered Horse Power 350Engines made at Sunderland By whom J. Dickson & SonsWhen 1906-3No. of Main Boilers 254Boilers, when made (Main) 1906(Donkey) 1906When 1906No. of Donkey Boilers 1Owners Broderick & Co.Port Bergen

Voyage

Steam Pressure in Main Boilers 180 lb.If Surveyed Afloat or in Dry Dock Commissioners' Dock

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

Last Report No. 3742 Port North ShieldsParticulars of Examination and Repairs (if any) HP cylindersCHARACTER. + for Special Survey. 8-16Year Assigned 1916

Machinery and Boiler Surveys (including date of N.B., if any).

+100A1+LmC8-1612-13Proposed 2 14B.S. 2 16T.S. 12-15

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? noDo. " Donkey " noIf this was not done, state for what reasons? not due B.S. not Submitted for Survey

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Has screw shaft now been drawn and examined?

Is it fitted with continuous liner?

or two liners?

or is it without liners?

Has shaft now been changed?

If so, state reasons

Is the shaft now fitted new?

Has it a continuous liner?

or two liners?

or is it without liners?

State the distance between lignum vite of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Damage to HP bottom cover of HP cylinder, no particulars furnished - Attended on board for the purpose of examining the bottom cover (forming the piston stuffing box of the High pressure cylinder) of the High pressure cylinder found that the High pressure bottom cover had been taken down, the piston being drawn to effect this, upon examination found that a small piece of the flange, forward side broken off extending to & through two stud holes leaving about 1" of flange adjacent to spigot uninjured - found no further evidence of defect - It was arranged that the broken piece of flange should be kept in place by a circumferential shop of steel being studded on to the broken piece & adjacent sound part and a flat plate extending over the broken part to the studs on each side of the broken part - It is understood that a new bottom cover has been ordered from the Engine

General Observations, Opinion, and Recommendation:—

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9, 11, B.&M.S. 9, 11, or S.L.M.C. 9, 11, 14 lb., F.D., &c.

In my opinion the machinery is now so far as seen in good working order and eligible to remain as classed in the Register Book, subject to the bottom cover of the High pressure cylinder being renewed, (or further examined) on or before the end of November 1916 -

Survey Fee (per Section 25) £  
(See entry Certificate) £  
Special Damage or Repair Fee (if any) £2.2.0  
(per Section 25.)  
Travelling Expenses (if chargeable) £

Fees applied for

21 SEP 1916

21 SEP 1916

Leonard Shallerross

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI. 6-OCT. 1916FRI. DEC. 8-1916

Assigned

As per subject.

Lloyd's Register Foundation

W906-0101 1/2







eps. Finn

Builders - and will be fitted in due course.  
At the request of the Captain a sea worthy certificate was  
issued, to cover a period of two months.

Leonard & Shalloo.



© 2021

Lloyd's Register  
Foundation