

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 24th APR. 1947, When handed in at Local Office 19 Port of DUBLIN.
 No. in Survey held at RUSHBROOK, Date, First Survey 10th FEB. Last Survey 22nd APRIL, 1947.
 eg. Book. (No. of Visits 2.)
60867 on the Wood, Iron or Steel TWIN S. "MURCHU"
 TONNAGE:— Built at DUBLIN By whom DUBLIN DOCKYARD CO. When 1908. MONTH 7
 GROSS 323 Owners GOVERNMENT OF IRE (DEPT. OF AGRICULTURE) Owners' Address
 UNDER DK. 265 Managers (if not already recorded in Appendix to Register Book).
 NET 111 Port belonging to DUBLIN.

Surveyed Afloat or in Dry Dock? DRY DOCK Name of Dock RUSHBROOK Destined Voyage
 Cell DBor DBa feet; uE&B feet; f feet
 Total capacity tons. FPT tons; APT tons; MT feet tons. } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 6217. Port Dub.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined yes. Not

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

required.

Was a damage report made by anyone else? if so, by whom? No.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage alleged to have been sustained through ranging and bumping Quay Wall at Haulebowline during gales on 6th to 8th February 1947.

done:—Vessel placed in dry dock bottom keel and rudder examined and placed in efficient condition.

found Starboard side, shell plate E7 from aft chafed, rubbing bar in way started, rivets loose and broken. This has increased previous damage and not stated.

Temporary Repairs.

Rubbing bar released and approx. 50 rivets in bar and shell plate E7 renewed.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

PRESENT CONDITION OF THE

good	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
ing of Decks	Ceiling	Coal Bunkers	When fitted, Month Year
ings	Cement or Asphalt	Oil Bunkers	Boats
s & Fastenings	Rudder	Scuppers	Masts, <u>Good</u>
ie Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained <u>FROM DECK.</u>
.. in way of sidelights	Windlass	Hatches	(State if wedges removed.)
es	Have pumps been examined and found efficient?	Planking	Equipment letter
se Frames	Have Sluice Valves been examined and found efficient?	Caulking	Anchors, No. of <u>3.8, 1.5,</u>
udinals	Have Watertight Doors been examined and found efficient?	Treenails	Cables (State if now ranged) <u>No.</u>
erases	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	length mean diamr.
is	Air and Sounding Pipes	Transoms, Pointers & Crutches	(on board)
rs.	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Rule length size
Bottom Plating		" " at other places	Chain Locker
ie Tanks been examined internally		Stringers, Clamps & Shelves	Hawsers & Warps
ie Tanks been tested?		Salting (State if examined.)	Standing and Running Rigging <u>Good</u>
			Sails

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without 'fresh record of Survey,'" "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

this vessel so far as now seen is in efficient condition and eligible in my opinion to remain as classed with fresh record 4.47. Suggested Renew shell plate E2 (SSA) B2 & 3 (SSA) first opportunity Renew 15" F. wire cable first opportunity. Upper deck stanchion fore and aft & bridge to be dealt with as SS. Suggested shell plate E7, E7, B6 & 7 (SS)

Survey Fee (per Section 20) <u>INF. CHAT</u>	£ 5	: 5	: 0	Fees applied for, <u>24 APR 1947.</u>
Special Damage or Repair Fee (if any) <u>(per Sec. 20)</u>	£ 5	: 5	: 0	Received by me, <u>R. B. Lynes.</u>
Printing Expenses (if chargeable)	£ 4	: 6	: 3	19
and Surveyor's Fee (if any)	£	:	:	


Committee's Minute

Character Assigned

FEB. 30 MAY 1947

Deferred for comp. S. B. (m)
 but assign 4.47 Dub subject

Surveyor to Lloyd's Register of Shipping



Lloyd's Register Foundation

Concrete box fitted in way.
Repairs were tested and found tight.

This vessel has been sold to Messrs Hammond Lane Metal Co. Ltd.
Dublin and is to be broken up on arrival at Dublin.
Interim Certificate issued to new owners copy attached.

Nothing done at this time examined and found efficient.

R. B. Green.

Vessel in dry dock examined bottom, keel & rudder, Deck, casings, hatchways, steering gear, windlass, equipment, ventilator, found in good condition.

R.B.E.

ANCHORS.

[illegible]

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN



REPORT

te of writing Rep

. in Surve
Book.

867. on t

Surve

For c

and

Regist

recom

that

with

being

五五

This Certificate
"While the C
ecuted, it is to
whatever to be he
ntry in the Regis
committees or an

rt. B.)—20m, 2, 40. (1

200 1000

Special Dan

Travelling e

Committee

Assigned



© 2020

Lloyd's Register
Foundation