26063

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office)

No. 38/43.

No. in Reg. Book. 1159

Survey held at London — Date, first Survey 20 Dec^r — Last Survey 20 December 1879

on the S.S.^r "Miranda" — Master Keyo

TONNAGE under Tonnage Deck	845	Built at Newcastle	When built 1865
Ditto of Spar Deck, or Awning Deck		Owners London Stm Sh Co	Port belonging to London
Ditto of Poop		Residence	
Ditto of Raised Qr. Dk.		By whom built Palmer	Destined Voyage Cardiff - 2y Tyne
Ditto of Houses on Deck		If Surveyed Afloat or in Dry Dock (State Name of Dock)	limekiln dry dock
Ditto of Forecastle			
Gross Tonnage	996		
Crew Space, as per Rule			
Register Tonnage, cut on Beam			
Engine Room			
Reg. Tons as St'mer, cut on Bm.	736		

Official Number

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

Classed — Years assigned — Character in Register Book. 8 0 A1 S.S. No 2. 77.

Last Survey, No. 24929 **Port** Iron

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

This Vessel has recently been reported by Mr Tyrrell from Cardiff at which port a leak was discovered, and it was found to have arisen from a hole in the plate next the garboard in the well on the port side just before the Boiler bulkhead. And a large rivet was fitted to fill the hole referred to

She has now been placed into dry dock as per com^n, and two visits were made with the view to an examination of the bottom, but on each occasion the water and mud deposit in the dock prevented any survey being made.

It was arranged that a liner plate be fitted in way of the hole plate, and in addition that several started rivets

Present Condition		Trenails	Good	Windlass and Capstan	Good
Decks	Good	Breasthooks and Stemson	do	Pumps	do
Waterways	do	Transoms, Pointers, and Crutches	do	Boats	do
[illegible]	do	Timbers of the Frame at the openings	do	Masts, Yards, &c.	do
& Beam [illegible]nings	do	Ditto Ditto at other places	do	Condition, how ascertained	on deck
Plate [illegible]Fastenings	do	Keelsons	do	Sails	well found
[illegible] Cap	do	Clamps and Shelfs	do	Anchors No. of	2 B. 1 K. 1 Kedge
Sheerstrake	do	Ceiling	do	Cables	complete
Topsides	do	Rudder		Hawsers and Warps	sufficients
Wales	do	Copper (or Y.M.) ✓ When put on ✓		Standing & Running Rigging	do
Plank (Bottom) and Counter	do	Caulking of Bottom, Deck, & Waterways	do		

Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers Good — Cargo and Main Hatchways Good — Hatches Good

General Observations, Opinion as to Class, &c.

This Vessel as far as can be examined appears in good condition and eligible to remain as classed, but as regards the work now done and which has not been seen, it is submitted that the Vessel should be placed under Survey as early as possible for the Survey to be completed

The Amount of Entry Fee ... ...£ : : received by me, 18

Special ... ...£ : :

Certificate (if required) to be sent as per margin... £ : :

(Travelling Expenses, if any, £)

Thr. Longdon

Surveyor to Lloyd's Register of British and Foreign Shipping

Committee's Minute 23rd December, 1879.

Character assigned 8 0 A 1 as now, subject to further Survey as proposed by Surveyor

3.79 [illegible] Note the Case

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

[4,000—11/10/79.]

ROBT. EDMD. TAYLOR & SON, Commercial Steam Printers, 19, Old Street, Goswell Road, London.

IRON491-0227

© 2019 Lloyd's Register Foundation