Engine Room ..
Gross Tonnage 134.53
Less Crew Space 61.18

Depth "d," at middle of length (See Secs. 2 & 13) ....

Managers E.A. Casper, Edgar ... West Hartl...

W755-0139
W755 0138

4m,8.15.

for full purposes

Received by Chief Ship Surveyor 27. 10. 15.

Received from Chief Ship Surveyor 27 OCT 1915

VESSEL'S NAME Stl. Sc.Sr. "SPIRAL". Rpt. W.Hpl. No.15169 A

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Nature of Survey 1st Entry & No. 3 Damage.
Classification

RETAIN

This vessel was built by the Nylands Mek Verksteds of Christiania in 1906, and classed 1A1 in the Norske Veritas.

The vessel was stranded at Redcar in March last but was salved and placed in dry dock at Hartlepool.

In August last the Hartlepool Surveyors forwarded plans of the Midship Section and Profile and deck plans which were supplied by the new Owners, who wished them to be examined with a view to the vessel being classed in the Register Book.

It was found that the Scantlings and arrangements were equivalent to the requirements of the Society's Rules for the 100.A1.class for the year in which the vessel was built, provided 75 fathoms of $3\frac{3}{4}$" steel wire and 180 fathoms of 5" hawser or $1\frac{3}{4}$" steel wire be added to the equipment now on board.

A report has now been received from the Hartlepool Surveyors from which it appears that the Scantlings of the vessel have been verified, and the requirements of Section 48 of the Rules complied with, also the requirements for the Special Survey No.3; and the ropes referred to above supplied.

The following repairs due to damage sustained thro Stranding have now been carried out:-

97 shell plates renewed; 31 renewed, faired and refitted, and 14 faired in place. 175 frames renewed and 31 part renewed;

P.T.O.

© 2020 Lloyd's Register Foundation

Dry Dock

No. of Decks w...
No. of Tiers of...
Round of U... Dk. Beam,...

Inches. Size in Ship. | Inches Spacing in Ship.
2.5/8 | 4...
3½ | "

Inches in Ship. | Inches in Ship.

Two
4½
3

35

"
... × 4½

20
... × 3
10
4. Pins
36
3 × 3

Double Angles, Plate, ... Channels,
" Angles on upper edge ....
" Spacing ....
" Tie Plates ....
" Deck. Material and thickness
Bridge Deck Stringer Plate, br'dth & thickness