

J. S. Strathleven

N.H. 324<sup>th</sup>

It is submitted that before dealing with this case the surveyors should be requested to state clearly what recommendations were made with reference to the intermediate low pressure crank shafts being out of line and the flaw found in the 5<sup>th</sup> length of tunnel shafting; also whether these recommendations were carried out. They should also be requested to state to state for how long they consider the tunnel shaft to be in a safe working condition.

With regard to the Boiler survey the surveyor should be requested to state in detail the result of his examination of the Boilers & also whether he examined and afterwards adjusted under steam the safety valves. With reference to the donkey boiler he should state whether in his opinion the condition of this boiler is such as to render it <sup>only</sup> eligible for a working pressure of 45 lbs in view of the pressure previously assigned being 54 lbs.

For preference the report should be made on the report form I provided for the purpose

Dr. to N.H.

28/10/98

JS

27/10/98



© 2018

Lloyd's Register  
Foundation