

26395
S, &c. 11/2/91

No. _____ of the Ship _____

P. R. Edwards

Last Survey, No.	8283	Port	Hpl + Lmc 11-90	Classed Carrying Petroleum in Bulk	+ 100 A1
				S.S. Hpl 201-90	190

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

Pointed out to the Owner's representative that the Cement in the water ballast tanks required to be examined, and that facilities should be afforded for the survey of the same, he however stated that owing to the shortness of time it was impossible to open the tanks out and clean them for this purpose at present. Please see his letter hereto attached.

Engine Room Skylights *Good* Coal Bunker, Openings, Lids, &c *Good* Scuppers *Good* Cargo & Main Hatchways *Secure* Hatches *Good*
General Observations, Opinion as to Class, Recommendation, &c. :- This vessel appears to be in good and efficient condition as far as could be seen and eligible in my opinion to remain as classed + 100A1 without fresh record until the cement be examined

Committee's Minute FEB 9 OCT 1891 TUES. 22 MAR 1892
Character assigned Defered for
Examⁿ of Cement.
Asph. Mr. Brown 10/10/91