

8 OCT 1917

ed by Chief Ship Surveyor 2-10-17

Received from Chief Ship Surveyor

VESSEL'S NAME Iron S.S. "Stettin"

Rpt. Hwc. No. 40306.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

State of Survey

DAMAGE. (see also hwc. rpt. no. 40069).

Damage through Striking Quay wall.

now repaired as follows:-

	Plates	Frames R.	Frames	Floors	Beams	Str.	Plates	Dk.	Plates
Renewed	6	2 partly							
Removed and faired or repaired.....	-	-							
Faired or repaired in place.....	-	-							

Other items:-

Vessel examined in dry dock, bottom cleaned & coated,
stem bar cropped, removed, faired and refitted and electrically
welded at both.

A new bow anchor placed on board.
Minor repairs effected.

It is submitted the vessel is worthy to remain as classed with
record of Survey 9-1-17 as recommended without special conditions
as regards stem plating, frames etc.

+ A1 } without etc
9-1-17 hwc.



© 2018

Lloyd's Register
Foundation