

REPORT of SURVEY for REPAIRS, &c.Date of writing Report 26th Oct 1931 When handed in at Local office 26th Oct 1931 Port of Leith

No. in Reg. Book Survey held at Leith

Date, First Survey 15th Oct 1931 Last Survey 20th Oct 1931
(No. of Visits)

35134 on the Wood, Iron or Steel 75' Stettin

TONNAGE:-

GROSS 876

UNDER DL 857

NET 528

Built at Glasgow By whom Batclay, Burle & Co When 1864

Owners Leith Hull & Hamburg S.P.C. & Owners' Address

(if not already recorded in Appendix to Register Book).

Managers J. Currie & Co.

Port belonging to Leith

Surveyed Afloat or in Dry Dock? Drydock Name of Dock Prince of Wales Destined Voyage Containment.

WB=CellDBorDBa feet; uE&B feet; f feet total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 17802 Port Lth

(Periodical Survey, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarized in the form given below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the date and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Particulars of Classification (which must be inserted preceding as in Register Book & Supplements).

CHARACTER	YEAR	MONTH
+ A 1 5.30	L M C	229
se 100 5.40 3 -	+ N B	11.26
11.26	B S	5.30
5.3. Lth No 1-29	T S N	5.30
	N D B	14

Society's Freeboard (if assigned) as painted on Ship and now verified 2 ft 5 1/2 in ✓

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This vessel was placed in dry dock. The rudder & bottom were cleaned & examined, & were afterwards recoated. One shall plate on the starboard side of the Engine Room was found somewhat wasted, in way of a scupper pipe. A doubling plate has been fitted over the affected part.

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors	Beams	Sp. Plates	Dk. Plates	Other Items
Removed								
Removed and Fairing or Repaired								
Fairing or Repaired in place								

PRESENT CONDITION OF THE

Decks	Good	Stand of Tanks have been examined inside	No	Dring. Plates under Scouring Pipes	✓	Copper, or T.M. of Wood Vessels	✓
Caulking of Decks	.	State of Tanks now tested	.	Engine Room Skylights	Good	When put on, Month	Year
Ceilings	.	Bulkheads	Good	Coal Bunkers, Open'g, Lids, &c.	.	Boats	Good
Beams & Partitions	.	Ceilings	.	Stoppers	.	Masts, Yards, &c.	.
Outside Plating	.	Cement of Asphalt	.	Cargo Hatchways	.	Condition, how ascertained	.
Breasthooks	✓	(state which.)	.	Hatches	.	(state of wedges removed)	.
Transoms	✓	Roofing	.	Planking	of Wood Vessels	Sails	.
Frames	Good	Scouring gear and its connections	.	Caulking	ditto	Equipment letter	✓
Reverse Transoms	.	Welding	.	Transom	ditto	Anchors, No. id	3 B 2 S 1 K
Longitudinals	✓	Have Pumps now been examined and found effec-	Not examd	Breasthooks & Stoppers	dito	Cables (state if now ranged)	No
Transverses	✓	ciant?	.	Transom, Pintles, & Cringles	dito	... length (row board)	Reported
Floors	✓	Have Valve Valves now been examined and found	.	Timbers (Fracture, splitting)	dito	... Breadth (row board)	complete
Kitchens	✓	sound?	.	Data	etc Charpied	Stringers, Gamps & Shells	Sufficient
Stringers	✓	Have Watertight Doors now been examined and found	efficent?	Backing	dito	Hoist & Warps	Good
Base Bottom Plating	✓	sound?	good	(state if examined)		Standing and Running Rigging	Good

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey 124, and the notations of No. 1-24 and pN24, &c."

This vessel appears to be in an efficient condition & is eligible in my opinion to remain as classed with fresh record of Survey 10-31.

Survey Fee (per Section 29) £

Fee applied for £

Special Damage or Repair Fee (if any) £

19

Travelling Expenses (if chargeable) £

Received by me

Second Surveyor's Fee (if any) £

19

Committee's Minutiae

TUE. 3 NOV 1931

Character Assigned

B 1
10.31John Houston
Surveyor to Lloyd's Register of Shipping.

© 2018

Lloyd's Register
Foundation