

REPORT of SURVEY for REPAIRS.

31991

No. in Reg. Book. *145* No. *31268* Survey held at *Londre* Date, first Survey *1870* Last Survey *16 Nov 1871*
 on the *Ship Thermopylae* Master *R. Kemball*
 Tonnage *947* built at *Aberdeen* When built *1868* *8 mo*
 By whom built *Hood* Owners *Thompson & Co*
 Port belonging to *Aberdeen* Destined Voyage *Melbourne*
 If Surveyed Afloat or in Dry Dock *(Afloat dry dock and afloat)*
 Last Survey, No. *31268* Port *Londre* Classed *1741*
 REPAIRS, &c. *Iron frame planked* *cf. 1170*

Being in flat of bottom removed all pine and aft on each side, the parts exposed cleaned and painted and the cement coating raised to upper part of floors.

Frames &c in lower hold cleaned and painted and the Yellow Metal sheathing on bottom patches.

Present Condition of the

Decks	Treenails	Windlass and Capstan	<i>Good</i>
Waterways	Breasthooks and Stemson	Pumps	<i>Good</i>
Comings	Transoms, Pointers, and Crutches	Boats	<i>Good</i>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	<i>Good</i>
er Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	<i>Upon the deck</i>
Sheers	Keelsons	Sails	<i>Good</i>
Strakes	Clamps and Shelves	Anchors No. of	<i>Good</i>
Sides	Ceiling	Cables	<i>Good</i>
les	Rudder	Hawsers and Warps	<i>Sufficient</i>
	Copper <i>Yellow</i> When put on <i>1870</i>	Standing & Running Rigging	<i>Good</i>
	Caulking of <i>3</i>	Cargo and Main Hatchways	<i>Good</i>
	Bottom, Deck, & Waterways	Hatches	<i>Good</i>
	Coal Bunker, Openings, Lids, &c.	Scuppers	<i>Good</i>
al Observations and Opinion,			

Known in good and efficient condition, and in my opinion eligible to remain as classed.

M. S. Surnes

ent of Entry Fee.....£ : : is received by me,

Special.....

Certificate (if required).....

inate *21st November* 18 *71*

rned



© 2018

Lloyd's Register Foundation