

11.5.16

Received from Chief Surveyor's

ME

Shells

venger

Report

Gl

No. 35880

RVEYOR and CHIEF ENGINEER SURVEYOR.

For the CHIEF SHIP

Committee "the endorsement to contain a succinct summary of any repairs that have been made which have to be submitted to the Classing Committee, such repairs, and also to bring out clearly any exceptional features in connection with the case required and to show the cause or cause the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/72.) so that the Classing Committee may

July—

When due

- * 100A.1 (Steel) Shells Deck with platform
3 B.H. (Upper - 2 B.H. Steel ws) + Shells dr (Steel Tubs)
Cuu DB 414' 1389 G. FPT 99 G A.P.T. 274 G
FK + BH 2. " 1 Twin dr B.H. dispensed with. 1 BH to Shells deck,
7 BH. to upper deck, 3 BH to lower deck only."
"pl. cur. L. a.s.d. to Shells dr 90."

M
11.5.16



© 2018
Lloyd's Register
Foundation