

Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

EL'S NAME *Stat S.S. "ARLIGHT"*Report *Js*No. *41433***For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/6/92.)

of Survey \_\_\_\_\_

When due \_\_\_\_\_

✱ 100. A-1. (Steel)

100k (Steel) Well Deck

Cell DBf 93' 129t, FPT 78t, APT 33t

BK 7 $\frac{1}{4}$ ", 3BK, Cam, Hlydo A. C., Q 100' BQ' F 33' Mely AftSee letter  
9.11.21*M**HW*20.10.21

It is concluded a web frame is fitted on frame N°86 as approved; ~~and~~  
~~that~~ two 4" hand pumps are fitted, and the Sig. of the Margin Angle  
 to the floor is as approved and not as stated but the Surveyors should  
 be requested to state if this so.

*Js 7/11/21*

Lloyd's Register  
Foundation

002038-002050-0275