

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME

Sheela Masula

Report

SB

No. 38837

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due

The Downton pump has been dispensed with for the present and it is concluded the Owners are agreeable to fit same at the end of the War if requested to do so.

100A-1 (Steel)

2 Dks (Steel)

Call DB 396 1551E F.P.T. 120E. A.P.T. 67E

FK. 7134. Cen. Log. axep. P44 B149 F41

M
19.6.19

It is concluded the brackets at helix are extended above the tank top in accordance with the approved plan, but the Surveyor should be requested to state if this is so & also to forward the approved plan of the bulkheads with the report of the sister vessel.

Dr. 13/8/19.

M
19.6.19



© 2020

Lloyd's Register Foundation

002094-002100-0418