

Both main boilers with their mountings opened out and examined internally and externally and after repairs, the safety valves adjusted under steam to 200 lbs.

The following repairs are stated to have been carried out at this survey:-

- Crankshaft lifted, main bearings retalled, and re-aligned
- IP slide valve and face machined
- HP bottom end bearing retalled
- Thrust shoes skimmed up and forward bearing retalled
- Both steam pistons in feed pump renewed.
- 3 plates in funnel renewed.

Boilers

A few broken stays renewed in both boilers and some minor welding carried out.

The following inspection was made personally subsequent to the above survey:-

Vessel placed on the floating dock, propeller and all outside fastenings examined.

Main engine generally examined without opening out, all repairs verified and found in order.

All independent pumps, examined without opening out and tried under working conditions.

Electrical installation examined.

Pumping arrangements part opened out, examined and found in order.

Both main boilers with their principal mountings opened out, examined internally and found in order.



© 2020

Lloyd's Register
Foundation