

Clydefield

Observation

Wood covers to forward hatchway

Framing area deficient

Ventilation well protected

Gangway appears to be efficient.

but no statement as to fore and aft bracing

S.B.



© 2020

Lloyd's Register  
Foundation

002101-002108-0164

*FREEBOARD REPORT on the*

It is submitted the Freeboards given on the accompanying  
form being those required by the Tables merit approval.



© 2020

Lloyd's Register  
Foundation