

Steel S.S. "Jean" Npl News N° 284

It is submitted that before this case receives the consideration of the Committee, The Newport News Surveyor should be requested to state whether, if the ~~joint~~ continuous line on the screw shaft is no more than one length, the joint has been burnt, as required by the Rules page 44 Sec 8 par 3. It should be pointed out to the Surveyor that a lapped joint not burnt has never been approved.

A.R.R.

14.8.09

Wt :- 14/8/09



© 2020

Lloyd's Register
Foundation

er does not fit
corrosive 7/9
of stern bush
ebs 25 1/2 x 8 1/4 Dia
Total surface
YES
YES
ted to both Bilg
2; 2-3"
ted in Engine roo
e room bulkheads
FS
ove or below the de
a spigot and bras
YES
YES
shaft and Prop
Main d
TESVILLE
S.E. M
o. of Certific
and Descripti
Are they fitted
10" Material o
of riveting: c
width of bu
hole in shell
ial S Out
No. of streng
9/16 Top
Working m