

In reply to your letter of the 5. Inst
with reference to the Screw Shaft of

002320-002329-0141

Luth Rpt- no 10518.

Submitted before this case reaches the
consideration of the Committee the Luth
Surveyor should be referred to his letter of
7 days date, & requested to state definitely
whether the dia. ~~7.6~~ of propeller as per Rpt
is correct or whether it should be 7.2"
as it is not made clear in his letter.

Dr. to Lth

11/9/03

11.9.03

11.9.03

of the shaft would meet the requirements
of the rules. I am Sir
Your Obedient Servant

Are they fitted with
3 7/8 Material of sh
Lap long. seam
traps 1'-
in shell 15
Outside
To. of strengthen
Top 1/2
Working pressur
End pl
Material
ont plates at b
ressure of plate
Mean pitch o
Material
Stays in each
e shut off and
udinal joint
Thic
How stayed